

序号	报告编号	发布日期	结论	影像资料
58	GX-B1328/20-6-24139	2024/12/25	所检项目合格。	
59	GX-B1328/20-6-24140	2024/12/25	所检项目合格。	

60	GX-B1328/20-6-24141	2024/12/25	所检项目合格。	
61	GX-B1598/24-6-24159	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.99%，小于5%为正常。	
62	GX-B1598/24-6-24160	2024/12/25	实测钢丝绳有效截面积损失百分比最大为1.23%，小于5%为正常。	


63	GX-B1598/24-6-24161	2024/12/25	实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。	 <p>2024-11-21</p>
64	GX-B1598/24-6-24162	2024/12/25	实测钢丝绳有效截面积损失百分比最大为1.13%，小于5%为正常。	 <p>2024 11 21</p>
65	GX-B1598/24-6-24163	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.24%，小于5%为正常。	 <p>2024 12 06</p>

66	GX-B1598/24-6-24164	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.21%，小于5%为正常。		
67	GX-B1598/24-6-24165	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.29%，小于5%为正常。		
68	GX-B1598/24-6-24166	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.29%，小于5%为正常。		


69	GX-B1598/24-6-24167	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.31%，小于5%为正常。	
70	GX-B1598/24-6-24168	2024/12/25	实测钢丝绳有效截面积损失百分比最大为2.26%，小于5%为正常。	
71	GX-B1598/24-6-24169	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.63%，小于5%为正常。	

72	GX-B1598/24-6-24170	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.72%，小于5%为正常。		
73	GX-B1598/24-6-24171	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.64%，小于5%为正常。		
74	GX-B1598/24-6-24172	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.63%，小于5%为正常。		

75	GX-B1598/24-6-24173	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.77%，小于5%为正常。	 <p>2024 12 06</p>
76	GX-B1598/24-6-24174	2024/12/25	实测钢丝绳有效截面积损失百分比最大为0.59%，小于5%为正常。	 <p>2024 12 06</p>
77	GX-B1310/21-6-24393	2024/12/26	符合标准要求.	 <p>2024 12 04</p>


78	GX-B1427/21-6-24104	2024/12/26	符合标准要求.	 A worker wearing a red hard hat and a grey jacket is standing in an industrial yard. In the background, there are stacks of metal pipes and a building. The date '2024 12 04' is visible in the bottom right corner of the photo.	
79	GX-B1310/21-6-24401	2024/12/27	符合标准要求	 A worker wearing a red hard hat and a grey jacket is standing near a large industrial machine. The machine has yellow and black safety railings. The date '2024 12 24' is visible in the bottom right corner of the photo.	
80	GX-B1310/21-6-24402	2024/12/27	符合标准要求	 A worker wearing a red hard hat and a grey jacket is using a measuring tool on a large industrial machine. Another worker is visible in the background. The date '2024 12 24' is visible in the bottom right corner of the photo.	

81	GX-B1612/23-6-24026	2024/12/30	所检项目合格。	 <p>2024 12 01</p>
82	GX-B1611/23-6-24010	2024/12/30	所检项目合格	 <p>2024 12 23</p>
83	GX-B1611/23-6-24009	2024/12/30	所检项目合格	 <p>2024 12 23</p>

84	GX-B1611/23-6-24008	2024/12/30	所检项目合格	 <p>2024 12 23</p>
85	GX-B1310/21-6-24400替代报告编号:GX-B1310/21-6-24388	2024/12/30	符合标准要求	 <p>2024 12 03</p>
86	GX-B1598/24-6-24175	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.24%，小于5%为正常。	 <p>2024 12 02</p>

87	GX-B1598/24-6-24176	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.31%，小于5%为正常。		
88	GX-B1598/24-6-24177	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。		
89	GX-B1598/24-6-24178	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.27%，小于5%为正常。		

90	GX-B1598/24-6-24179	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.37%，小于5%为正常。		
91	GX-B1598/24-6-24180	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.41%，小于5%为正常。		
92	GX-B1598/24-6-24181	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.05%，小于5%为正常。		

93	GX-B1598/24-6-24182	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.06%，小于5%为正常。	 <p>2024 12 01</p>	
94	GX-B1598/24-6-24183	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.09%，小于5%为正常。	 <p>2024 12 01</p>	
95	GX-B1598/24-6-24184	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.15%，小于5%为正常。	 <p>2024 12 01</p>	

96	GX-B1310/21-6-24394	2024/12/31	符合标准要求	
97	GX-B1310/21-6-24395	2024/12/31	符合标准要求	
98	GX-B1310/21-6-24396	2024/12/31	符合标准要求	

99	GX-B1310/21-6-24397	2024/12/31	符合标准要求	 A worker wearing a red hard hat and a grey jacket is working on a large green industrial machine. The machine has several circular openings and is situated in a factory setting. A date stamp '2024.12.17' is visible in the bottom right corner of the photo.
100	GX-B1310/21-6-24398	2024/12/31	符合标准要求	 A worker wearing a red hard hat and a grey jacket is working on a green industrial machine. The machine has a complex internal structure with many green components. A date stamp '2024.12.17' is visible in the bottom right corner of the photo.
101	GX-B1310/21-6-24399	2024/12/31	符合标准要求	 A worker wearing a red hard hat and a grey jacket is working on a green industrial machine. The machine has a complex internal structure with many green components. A date stamp '2024.12.17' is visible in the bottom right corner of the photo.

102	GX-B1427/21-6-24107	2024/12/31	符合标准要求	
103	GX-B1427/21-6-24108	2024/12/31	符合标准要求	

104	GX-B1598/24-6-24185	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。	
105	GX-B1598/24-6-24186	2024/12/31	实测钢丝绳有效截面积损失百分比最大为0.96%，小于5%为正常。	
106	GX-B1598/24-6-24187	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.04%，小于5%为正常。	

107	GX-B1598/24-6-24188	2024/12/31	实测钢丝绳有效截面积损失百分比最大为1.01%，小于5%为正常。	
108	GX-B1598/24-6-24189	2024/12/31	实测钢丝绳有效截面积损失百分比最大为0.95%，小于5%为正常。	
109	GX-B1598/24-6-24190	2024/12/31	实测钢丝绳有效截面积损失百分比最大为0.87%，小于5%为正常。	