

序号	报告编号	发布日期	结论	影像资料
65	GX-B1307/20-1-24037	2025. 1. 22	综合判定：合格。	
66	GX-B1307/20-1-24038	2025. 1. 22	综合判定：合格。	

67	GX-B1328/20-1-24066	2025. 1. 22	本次共检验电器6支， 6支所检项目合格。	
68	GX-B1328/20-1-24067	2025. 1. 22	本次共检便携式短路 接地线3套，3套所检 项目合格。	

69	GX-B1328/20-1-24068	2025. 1. 22	本次共检绝缘杆6支, 6支所检项目合格。	
70	GX-B1328/20-1-24069	2025. 1. 22	本次共检验电器4支, 4支所检项目合格。	

71	GX-B1328/20-1-24070	2025. 1. 22	本次共检便携式短路接地线2套，2套所检项目合格。	
72	GX-B1328/20-1-24071	2025. 1. 22	本次共检绝缘杆3支，3支所检项目合格。	

73	GX-B1328/20-1-24072	2025. 1. 22	本次共检验电器 18支，18支所检项目 合格。	
74	GX-B1328/20-1-24073	2025. 1. 22	本次共检便携式短路 接地线11套，11套所 检项目合格。	

75	GX-B1328/20-1-24074	2025. 1. 22	本次共检绝缘杆 16支，16支所检项目 合格。	
76	GX-B1328/20-1-24075	2025. 1. 22	本次共检验电器 24支，24支所检项目 合格。	

77	GX-B1328/20-1-24076	2025. 1. 22	本次共检便携式短路接地线12套，12套所检项目合格。	
78	GX-B1328/20-1-24077	2025. 1. 22	本次共检绝缘杆18支，18支所检项目合格。	

79	GX-B1328/20-1-24078	2025. 1. 22	本次共检绝缘胶垫24个，24个绝缘胶垫合格。	
80	GX-B1451/20-1-24650~24655	2025. 1. 22	本次共检高压开关设备6台，6台高压开关设备所检项目合格	



81	GX-B1451/20-1-24656~24661	2025. 1. 22	本次共检高压开关设备6台，6台高压开关设备所检项目合格	
82	GX-B1451/20-1-24662~24683	2025. 1. 22	本次共检高压开关设备22台，22台高压开关设备所检项目合格	

83	GX-B1322/21-1-25001~25018	1.22	本次共检验电力电缆 18条，18条所检项目 合格	
84	GX-B1322/21-1-25019~25027	1.22	本次共检验电力电缆9 条，9条所检项目合格	


85	GX-B1322/21-1-25028~25029	1. 22	本次共检验电力电缆2条，2条所检项目合格	
86	GX-B1322/21-1-24216~24226	2025. 1. 22	本次共检验电力电缆11条，11条电力电缆所检项目合格	

87	GX-B1322/21-1-24227~24238	2025. 1. 22	本次共检验电力电缆 12条，12条电力电缆 所检项目合格	
88	GX-B1328/20-1-24062	2025. 1. 22	本次共检验电器6支， 6支所检项目合格	

89	GX-B1328/20-1-24063	2025. 1. 22	本次共检便携式短路 接地线6套，6套所检 项目合格	
90	GX-B1328/20-1-24064	2025. 1. 22	所检项目合格	

91	GX-B1328/20-1-24065	2025. 1. 22	本次共检绝缘胶垫30块，30块所检项目合格	 <p>2024/12/28</p>
92	GX-B1598/24-1-25001	1. 22	实测钢丝绳有效截面积损失百分比最大为1.86%，小于5%为正常	 <p>2025/01/03</p>

93	GX-B1598/24-1-25002	1.22	实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常	
94	GX-B1598/24-1-25003	1.22	实测钢丝绳有效截面积损失百分比最大为1.66%，小于5%为正常	

95	GX-B1598/24-1-25004	1.22	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常	
96	GX-B1598/24-1-25005	1.22	实测钢丝绳有效截面积损失百分比最大为2.08%，小于5%为正常	

97	GX-B1598/24-1-25006	1.22	实测钢丝绳有效截面积损失百分比最大为2.14%，小于5%为正常	
98	GX-B1309/21-1-24033	1.22	所检项目合格	

99	GX-B1500/21-1-24133	1.22	综合判定：合格	 <p>2024/12/27</p>
100	GX-B1500/21-1-24134	1.22	综合判定：合格	 <p>2024/12/27</p>

101	GX-B1500/21-1-24135	1.22	综合判定：合格	
102	GX-B1329/21-1-25001~25017	2025. 1. 23	本次共检氧化锌避雷器17组，17组所检项目合格	

103	GX-B1495/20-1-25001~25012	2025. 1. 23	本次共检高压防爆开关设备12台，12台高压防爆开关设备所检项目合格	
104	GX-B1428/21-1-24299	2025. 1. 23	无缺陷痕迹显示	

105	GX-B1428/21-1-24300	2025. 1. 23	无缺陷迹痕显示	 <p>2024/12/27</p>
106	GX-B1328/20-1-24059	2025. 1. 24	本次共检验电器 10支，10支所检项目 合格	 <p>2024 12 26</p>

107	GX-B1328/20-1-24060	2025. 1. 24	本次共检短路接地线 10套，10套所检项目 合格	
108	GX-B1328/20-1-24061	2025. 1. 24	本次共检绝缘胶垫60 个，60个绝缘胶垫合 格	

109	GX-B1321/20-1-25001~25006	2025. 1. 24	本次共检电力电缆 6条，6条电力电缆所 检项目合格	
110	GX-B1312/20-1-25002	2025. 1. 24	所检项目合格	

111	GX-B1312/20-1-25001	2025. 1. 24	所检项目合格	 <p>2025/1/11</p>
112	GX-B1495/20-1-25013~25029	2025. 1. 24	本次共检高压开关设备17台，17台高压开关设备所检项目合格	 <p>6KV柜 同屏二柜 注意 反送电</p> <p>1.2.10.15.2025</p>