




序号	报告编号	发布日期	结论	影像资料
10	GX-B1342/21-8-22022	2022年10月14日	/	
11	GX-B1343/21-8-22027	2022年10月19日	/	
12	GX-B1343/21-8-22026	2022年10月19日	/	



13	GX-B1343/21-8-22025	2022.10.19	/	 <p>2022.6.1</p>
14	GX-B1347/21-8-22021	2022.10.19	/	 <p>2022.06.28 14:20</p>  <p>2022-06-28 17:22</p>
15	GX-B1341/21-8-22094	2022.10.12	综合判定：合格。	 <p>2022. 4. 21</p>

16	GX-B1343/21-8-22024	2022.10.19	/	 <p>2022.4.21</p>
17	GX-B1347/21-8-22020	2022.10.19	/	 <p>2022.4.21</p>
18	GX-B1340/21-8-22078	2022.10.12	<p>该通风机共测试3个状态（运行双级、叶片角度+6° /+6°：运行频率40Hz、42Hz、44Hz），所检项目合格。</p>	 <p>2022.7.10</p>







19	GX-B1347/21-8-22029	2022年10月20日	/	
20	GX-B1347/21-8-22030	2022年10月20日	/	
21	GX-B1340/21-8-22090	2022. 10. 20	所检项目合格	

22	GX-B1340/21-8-22086	2022. 10. 20	所检项目合格	
23	GX-B1340/21-8-22087	2022. 10. 20	所检项目合格	
24	GX-B1340/21-8-22085	2022. 10. 20	所检项目合格	

25	GX-B1340/21-8-22088	2022. 10. 20	所检项目合格	
26	GX-B1340/21-8-22089	2022. 10. 20	所检项目合格	
27	GX-B1340/21-8-22084	2022.10.20	合格	

28	GX-B1340/21-8-22083	2022.10.20	合格	
29	GX-B1343/21-8-22084	2022. 10. 20	综合判定合格	
30	GX-B1343/21-8-22085	2022. 10. 20	综合判定合格	

31	GX-B1343/21-8-22086	2022. 10. 20	综合判定合格		
32	GX-B1343/21-8-22087	2022. 10. 20	综合判定合格		
33	GX-B1343/21-8-22088	2022. 10. 20	综合判定合格		

34	GX-B1343/21-8-22089	2022. 10. 20	综合判定合格		
35	GX-B1343/21-8-22090	2022. 10. 20	综合判定合格		
36	GX-B1343/21-8-22091	2022. 10. 20	综合判定合格		

37	GX-B1343/21-8-22092	2022. 10. 20	综合判定合格	
38	GX-B1343/21-8-22093	2022. 10. 20	综合判定合格	
39	GX-B1341/21-8-22095	2022. 10. 20	综合判定：合格。	

40	GX-B1342/21-8-22020	2022年10月25日	合格	 
41	GX-B1594/21-8-22013	2022.10.25	该局部通风机共检5项，除流量、全压不判定外，其他所检项目均合格	
42	GX-B1342/21-8-22021	2022年10月26日	/	

43	GX-B1346/21-8-22013	2022. 10. 28	/	
----	---------------------	--------------	---	--