

序号	报告编号	发布日期	结论	影像资料
1	GX-B1306/21-Z-22005	2022/5/8	所检项目合格	
2	GX-B1306/21-Z-22006	2022/5/8	所检项目合格	
3	GX-B1306/21-Z-22007	2022/5/8	所检项目合格	

4	GX-B1306/21-Z-22008	2022/5/8	所检项目合格	 <p>2022 04 18</p>
5	GX-B1308/21-Z-22001	2022/5/8	所检项目合格	
6	GX-B1499/21-Z-22012	2022/5/8	所检项目合格	 <p>2022 04 24</p>

7	GX-B1499/21-Z-22013	2022/5/8	所检项目合格	
---	---------------------	----------	--------	---

8	GX-B1499/21-Z-22014	2022/5/8	所检项目合格	
---	---------------------	----------	--------	---

9	GX-B1499/21-Z-22015	2022/5/9	所检项目合格			
---	---------------------	----------	--------	--	---	--

2022 04 24

10	GX-B1499/21-Z-22016	2022/5/8	所检项目合格		 A photograph showing a person in a dark environment, possibly a tunnel or underground setting. The person is wearing a headlamp and is holding a handheld device that emits a bright light, illuminating the scene. The person appears to be working or inspecting something. The background is dark and indistinct.	
----	---------------------	----------	--------	--	--	--

2022 04 24

11	GX-B1339-21-Z-22001	2022/5/10	所检项目合格	 <p data-bbox="1787 810 1870 831">2022 04 25</p>
----	---------------------	-----------	--------	---

12	GX-B1339-21-Z-22002	2022/5/10	所检项目合格	 <p>The photograph shows two workers in a blue industrial environment. One worker, wearing a red hard hat and a blue uniform, is kneeling and operating a piece of equipment. The other worker, wearing a blue uniform, is kneeling next to him, looking at a device. A toolbox is open on the floor in the foreground, containing various tools and equipment. The date '2022 04 25' is visible in the bottom right corner of the photo.</p>
----	---------------------	-----------	--------	--

13	GX-B1339-21-Z-22003	2022/5/10	所检项目合格	
----	---------------------	-----------	--------	---

14	GX-B1339-21-Z-22004	2022/5/10	所检项目合格	
----	---------------------	-----------	--------	---

15	GX-B1339-21-Z-22005	2022/5/10	所检项目合格	 <p data-bbox="1666 852 1756 868">2022 04 25</p>
----	---------------------	-----------	--------	---

16	GX-B1381/20-Z-220007	2022/5/8	所检项目合格	
17	GX-B1385/21-Z-22013	2022/5/8	所检项目合格	

18	GX-B1310-21-Z-22009	2022/5/11	符合标准要求			
19	GX-B1307/20-Z-22002	2022/5/11	综合判定：合格			

20	GX-B1307/20-Z-22003	2022/5/11	综合判定：合格	
21	GX-B1307/20-Z-22004	2022/5/11	综合判定：合格	

22	GX-B1381-20-Z-220007	2022/5/9	所检项目合格		 A photograph showing two workers wearing red hard hats and light-colored work clothes. They are standing in an industrial setting, possibly a tunnel or underground facility, and are inspecting a complex structure of blue pipes and metal beams. The lighting is somewhat dim, and the floor appears to be concrete or stone.	
23	GX-B1423/20-Z-22001	2022/5/11	综合判定：合格		 A photograph showing three workers standing next to a large red truck. The workers are wearing white hard hats and work clothes. One worker is holding a white bag. The truck has the number '37' written on its side. The scene is outdoors on a dirt or gravel surface under a clear blue sky.	

24	GX-B1423/20-Z-22002	2022/5/11	综合判定：合格	
25	GX-B1423/20-Z-22003	2022/5/11	综合判定：合格	

26	GX-B1423/20-Z-22004	2022/5/11	综合判定：合格	 A photograph showing three workers in safety gear (hard hats, masks, and high-visibility vests) standing next to a green FAW truck. The truck has 'FAW' and 'PRODUCT OF FAW' visible on its side. A yellow timestamp '2022-05-03' is in the bottom right corner.
27	GX-B1423/20-Z-22005	2022/5/11	综合判定：合格	 A photograph showing three workers in safety gear (hard hats, masks, and high-visibility vests) standing next to an orange truck. The truck has the number '58' on its side. A yellow timestamp '2022-05-03' is in the bottom right corner.

28	GX-B1423/20-Z-22006	2022/5/11	综合判定：合格	
29	GX-B1423/20-Z-22007	2022/5/11	综合判定：合格	

30	GX-B1423/20-Z-22008	2022/5/11	综合判定：合格			
31	GX-B1423/20-Z-22009	2022/5/11	综合判定：合格			

32	GX-B1423/20-Z-22010	2022/5/11	综合判定：合格		 <p>2022 05 04</p>
33	GX-B1423/20-Z-22011	2022/5/11	综合判定：合格		 <p>2022 05 04</p>

34	GX-B1423/20-Z-22012	2022/5/11	综合判定：合格	
----	---------------------	-----------	---------	---