







序号	报告编号	发布日期	结论	影像资料
1	GX-B1517/20-7-22016	2022. 7. 1	合格	
2	GX-B1517/20-7-22017	2022. 7. 1	合格	
3	GX-B1517/20-7-22018	2022. 7. 1	合格	





4	GX-B1517/20-7-22019	2022. 7. 1	合格		
5	GX-B1517/20-7-22020	2022. 7. 1	合格		
6	GX-B1517/20-7-22021	2022. 7. 1	合格		
7	GX-B1517/20-7-22022	2022. 7. 1	合格		

8	GX-B1352/21-7-225336~225390	2022. 7. 4	合格	<p>说明</p> <p>中检集团公信安全科技有限公司： 因奥家村煤矿入井管理要求及保密规定，所有入井人员未经批准禁止井下拍照，因此现场检测照片未留存。 特此证明。</p> <p>2022年5月1日 奥家村煤矿中检</p>
9	GX-B1352/21-7-22428~22471	2022. 7. 4	合格	
10	GX-B1359/21-7-22175~22213	2022. 7. 4	合格	
11	GX-B1350/21-7-22094~22123	2022. 7. 4	合格	
12	GX-B1354/20-7-22010	2022. 7. 4	合格	
13	GX-B1404/20-7-22018	2022. 7. 4	合格	

14	GX-B1404/20-7-22019	2022. 7. 4	合格	
15	GX-B1404/20-7-22020	2022. 7. 4	合格	
16	GX-B1404/20-7-22021	2022. 7. 4	合格	
17	GX-B1358/21-7-22004	2022. 7. 4	合格	
18	GX-B1350/21-7-22041~22043	2022. 7. 4	合格	
19	GX-B1359/21-7-22093~22119	2022. 7. 4	合格	
20	GX-B1352/21-7-22287~22353	2022. 7. 4	合格	
21	GX-B1352/21-7-225175~225241	2022. 7. 4	合格	

22	GX-B1404/20-7-22032	2022-7-5	合格	
23	GX-B1404/20-7-22033	2022-7-5	合格	
24	GX-B1404/20-7-22034	2022-7-5	合格	
25	GX-B1404/20-7-22035	2022-7-5	合格	

26	GX-B1404/20-7-22036	2022-7-5	合格	
27	GX-B1404/20-7-22037	2022-7-5	合格	
28	GX-B1404/20-7-22038	2022-7-5	合格	
29	GX-B1404/20-7-22039	2022-7-5	合格	

30	GX-B1404/20-7-22055	2022-7-5	合格	 A photograph showing two workers in red hard hats and grey uniforms standing in a control room. They are positioned in front of a row of electrical control panels. A yellow safety barrier is visible in the foreground. The date '2022/6/14' is printed in the bottom right corner of the image.
31	GX-B1404/20-7-22056	2022-7-5	合格	 A photograph showing two workers in red hard hats and grey uniforms standing in a control room. They are positioned in front of a row of electrical control panels. A doorway is visible in the background. The date '2022/6/14' is printed in the bottom right corner of the image.
32	GX-B1404/20-7-22057	2022-7-5	合格	 A photograph showing two workers in red hard hats and grey uniforms standing in a control room. They are positioned in front of a row of electrical control panels. A control panel labeled '101' is visible. The date '2022/6/14' is printed in the bottom right corner of the image.
33	GX-B1404/20-7-22058	2022-7-5	合格	 A photograph showing two workers in red hard hats and grey uniforms standing in a control room. They are positioned in front of a row of electrical control panels. The date '2022/6/14' is printed in the bottom right corner of the image.