




序号	报告编号	发布日期	结论	影像资料
10	GX-B1370/21-9-22018	7.14	合格。	

11	GX-B1341/21-9-22080	7.14	综合判定：合格。	
12	GX-B1341/21-9-22081	7.14	综合判定：合格。	

13	GX-B1343/21-9-22019	7.14	无	
14	GX-B1347/21-9-22010	7.14	无	



15	GX-B1341/21-9-22082	2022. 7. 20	合格	 <p>2022.6.20</p>
16	GX-B1343/21-9-22020	2022. 7. 20	/	 <p>2022.6.20</p>

17	GX-B1340/21-9-22035	2022. 7. 12	合格	 <p>A photograph showing two workers in blue uniforms and red hard hats standing next to a large green industrial machine. The machine has the number '87154-411617' written on it. The ground is wet and reflective. A timestamp '2022.5.22' is visible in the bottom right corner of the photo.</p>
18	GX-B1340/21-9-22036	2022. 7. 12	合格	 <p>A photograph showing two workers in blue uniforms and red hard hats standing next to a large green industrial machine. The machine is partially covered with a grey tarp. The ground is wet and reflective. A timestamp '2022.5.22' is visible in the bottom right corner of the photo.</p>

19	GX-B1371/21-9-22004	2022. 7. 19	除上述问题外，其余所检项目合格。		
20	GX-B1371/21-9-22005	2022. 7. 19	除上述问题外，其余所检项目合格。		



21	GX-B1371/21-9-22006	2022. 7. 19	除上述问题外，其余所检项目合格。	
22	GX-B1341/21-9-22086	2022. 7. 21	综合判定：合格。	

23	GX-B1341/21-9-22087	2022. 7. 21	综合判定：合格。	 <p>2022年6月28日</p>
24	GX-B1341/21-9-22088	2022. 7. 21	综合判定：合格。	 <p>2022年6月28日</p>



25	GX-B1341/21-9-22089	2022. 7. 21	综合判定：合格。	
26	GX-B1341/21-9-22090	2022. 7. 21	综合判定：合格。	

27	GX-B1341/21-9-22091	2022. 7. 21	综合判定：合格。	 <p>2022年6月28日</p>
28	GX-B1341/21-9-22053	7. 21	综合判定：合格。	 <p>2022.5.23</p>



29	GX-B1341/21-9-22054	7.21	综合判定：合格。	
30	GX-B1341/21-9-22055	7.21	综合判定：合格。	

31	GX-B1341/21-9-22056	7.21	综合判定：合格。	
32	GX-B1341/21-9-22057	7.21	综合判定：合格。	

33	GX-B1341/21-9-22058	7.21	综合判定：合格。	 <p>2022.5.23</p>
34	GX-B1341/21-9-22059	7.21	综合判定：合格。	 <p>2022.5.23</p>

35	GX-B1341/21-9-22060	7.21	综合判定：合格。		 A worker wearing an orange protective suit, a hard hat, and a face mask stands in a dark, narrow tunnel. The worker is holding a flashlight, which illuminates the surrounding environment. The date '2022.5.23' is visible in the bottom right corner of the image.	
36	GX-B1341/21-9-22061	7.21	综合判定：合格。		 A worker wearing an orange protective suit, a hard hat, and a face mask stands behind a metal grid. The worker is holding a flashlight, which illuminates the surrounding environment. The date '2022.5.24' is visible in the bottom right corner of the image.	

37	GX-B1341/21-9-22062	7.21	综合判定：合格。	 <p>2022.5.24</p>
38	GX-B1341/21-9-22063	7.21	综合判定：合格。	 <p>2022.5.24</p>

39	GX-B1341/21-9-22064	7.21	综合判定：合格。		 <p>2022.5.24</p>	
40	GX-B1341/21-9-22065	7.21	综合判定：合格。		 <p>2022.5.24</p>	

41	GX-B1341/21-9-22066	7.21	综合判定：合格。	
42	GX-B1341/21-9-22067	7.21	综合判定：合格。	

43	GX-B1341/21-9-22068	7.21	综合判定：合格。	
44	GX-B1341/21-9-22069	7.21	综合判定：合格。	

45	GX-B1341/21-9-22070	7.21	综合判定：合格。	
46	GX-B1341/21-9-22071	7.21	综合判定：合格。	