









序号	报告编号	发布日期	结论	影像资料
373	X-B1309/21-6-2202	2022/7/29	合格	 A worker wearing a red helmet and camouflage uniform is working on a metal structure in a tunnel. The worker is holding a tool and appears to be inspecting or adjusting the structure. The background shows the rough, rocky walls of the tunnel. A timestamp '2022 06 22' is visible in the bottom right corner of the image.
374	X-B1309/21-6-2202	2022/7/29	合格	 A worker wearing a red helmet and camouflage uniform is standing on a metal structure in a tunnel. The worker is looking down at something in their hands. The background shows the rough, rocky walls of the tunnel. A timestamp '2022 06 23' is visible in the bottom right corner of the image.
375	GX-B1500/21-6-22089	2022/7/29	合格	 A worker wearing a red helmet and camouflage uniform is working on a piece of equipment in a tunnel. The worker is using a tool to work on the equipment. The background shows the rough, rocky walls of the tunnel. A timestamp '2022 06 22' is visible in the bottom right corner of the image.

376	GX-B1500/21-6-22090	2022/7/29	合格			
377	GX-B1500/21-6-22091	2022/7/29	合格			
378	GX-B1500/21-6-22092	2022/7/29	合格			
379	GX-B1500/21-6-22093	2022/7/29	合格			

380	GX-B1500/21-6-22094	2022/7/29	合格		 2022 06 21
381	GX-B1500/21-6-22095	2022/7/29	合格		 2022 06 21
382	GX-B1500/21-6-22096	2022/7/29	合格		 2022 06 23
383	GX-B1500/21-6-22097	2022/7/29	合格		 2022 06 23

384	GX-B1500/21-6-22098	2022/7/29	合格			
-----	---------------------	-----------	----	--	---	--