





序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-P-22061	2022. 8. 1	符合标准要求	
2	GX-B1310/21-P-22062	2022. 8. 1	符合标准要求	

3	GX-B1310/21-P-22063	2022. 8. 1	符合标准要求	
4	GX-B1417/22-P-22109	2022. 8. 1	综合判定：合格	
5	GX-B1417/22-P-22110	2022. 8. 1	综合判定：合格	

6	GX-B1417/22-P-22111	2022. 8. 1	综合判定：合格	
7	GX-B1417/22-P-22112	2022. 8. 1	综合判定：合格	
8	GX-B1417/22-P-22113	2022. 8. 1	综合判定：合格	

9	GX-B1417/22-P-22114	2022. 8. 1	综合判定：合格	
10	GX-B1428/21-P-22016	2022. 8. 4	符合标准要求	
11	GX-B1428/21-P-22017	2022. 8. 4	符合标准要求	

12	GX-B1417/22-P-22022	2022. 8. 4	所检项目合格	
13	GX-B1417/22-P-22023	2022. 8. 4	所检项目合格	
14	GX-B1417/22-P-22024	2022. 8. 4	所检项目合格	

15	GX-B1417/22-P-22025	2022. 8. 4	所检项目合格	 A worker wearing a red hard hat and a white t-shirt with a logo is inspecting the side of a white truck. The truck has a red fire extinguisher mounted on it. The date stamp '2022/7/17' is visible in the bottom right corner of the photo.
16	GX-B1417/22-P-22026	2022. 8. 4	所检项目合格	 A worker in a red hard hat and a grey t-shirt is inspecting the interior of a white van. The van's rear door is open, and the worker is looking into the cargo area. The date stamp '2022/7/17' is visible in the bottom right corner of the photo.
17	GX-B1417/22-P-22027	2022. 8. 4	所检项目合格	 A worker in a red hard hat and a white t-shirt is inspecting the engine compartment of a white truck. The truck has '载5人' (Carrying 5 people) written on its side. The date stamp '2022/7/17' is visible in the bottom right corner of the photo.

18	GX-B1417/22-P-22028	2022. 8. 4	所检项目合格		
19	GX-B1417/22-P-22029	2022. 8. 4	所检项目合格		
20	GX-B1417/22-P-22030	2022. 8. 4	所检项目合格		

21	GX-B1417/22-P-22031	2022. 8. 4	所检项目合格	
22	GX-B1417/22-P-22032	2022. 8. 4	所检项目合格	
23	GX-B1417/22-P-22033	2022. 8. 4	所检项目合格	

24	GX-B1417/22-P-22034	2022. 8. 4	所检项目合格	
25	GX-B1417/22-P-22035	2022. 8. 4	所检项目合格	
26	GX-B1417/22-P-22036	2022. 8. 4	所检项目合格	

27	GX-B1417/22-P-22037	2022. 8. 4	所检项目合格		
28	GX-B1417/22-P-22038	2022. 8. 4	所检项目合格		
29	GX-B1417/22-P-22039	2022. 8. 4	所检项目合格		

30	GX-B1417/22-P-22040	2022. 8. 4	所检项目合格		
31	GX-B1417/22-P-22041	2022. 8. 4	所检项目合格		
32	GX-B1417/22-P-22042	2022. 8. 4	所检项目合格		

33	GX-B1417/22-P-22043	2022. 8. 4	所检项目合格		
34	GX-B1417/22-P-22044	2022. 8. 4	所检项目合格		
35	GX-B1417/22-P-22045	2022. 8. 4	所检项目合格		

36	GX-B1417/22-P-22046	2022. 8. 4	所检项目合格		
37	GX-B1417/22-P-22047	2022. 8. 4	所检项目合格		
38	GX-B1417/22-P-22048	2022. 8. 4	所检项目合格		

39	GX-B1417/22-P-22049	2022. 8. 4	所检项目合格		
40	GX-B1417/22-P-22050	2022. 8. 4	所检项目合格		
41	GX-B1417/22-P-22051	2022. 8. 4	所检项目合格		

42	GX-B1417/22-P-22052	2022. 8. 4	所检项目合格	 <p>2022/7/18</p>
43	GX-B1417/22-P-22115	2022. 8. 5	综合判定：合格	 <p>2022/07/23</p>
44	GX-B1417/22-P-22116	2022. 8. 5	综合判定：合格	 <p>2022/07/23</p>

45	GX-B1417/22-P-22117	2022. 8. 5	综合判定：合格	 <p>2022/07/23</p>
46	GX-B1417/22-P-22118	2022. 8. 5	综合判定：合格	 <p>2022/07/23</p>
47	GX-B1417/22-P-22119	2022. 8. 5	综合判定：合格	 <p>2022/07/23</p>

48	GX-B1417/22-P-22120	2022.8.5	综合判定：合格	 <p>2022/07/23</p>
49	GX-B1417/22-P-22053	2022.8.5	所检项目合格	 <p>2022/7/19</p>
50	GX-B1417/22-P-22054	2022.8.5	所检项目合格	 <p>2022/7/19</p>

51	GX-B1417/22-P-22055	2022. 8. 5	所检项目合格	
52	GX-B1417/22-P-22056	2022. 8. 5	所检项目合格	
53	GX-B1417/22-P-22057	2022. 8. 5	所检项目合格	

54	GX-B1417/22-P-22058	2022. 8. 5	所检项目合格		
55	GX-B1417/22-P-22059	2022. 8. 5	所检项目合格		
56	GX-B1417/22-P-22060	2022. 8. 5	所检项目合格		

57	GX-B1417/22-P-22061	2022. 8. 5	所检项目合格		
58	GX-B1417/22-P-22062	2022. 8. 5	所检项目合格		
59	GX-B1417/22-P-22063	2022. 8. 5	所检项目合格		

60	GX-B1417/22-P-22064	2022. 8. 5	所检项目合格		
61	GX-B1417/22-P-22065	2022. 8. 5	所检项目合格		
62	GX-B1417/22-P-22066	2022. 8. 5	所检项目合格		

63	GX-B1417/22-P-22067	2022. 8. 5	所检项目合格		
64	GX-B1417/22-P-22068	2022. 8. 5	所检项目合格		
65	GX-B1417/22-P-22069	2022. 8. 5	所检项目合格		

66	GX-B1417/22-P-22070	2022. 8. 5	所检项目合格	
67	GX-B1417/22-P-22071	2022. 8. 5	所检项目合格	
68	GX-B1417/22-P-22072	2022. 8. 5	所检项目合格	

69	GX-B1417/22-P-22073	2022. 8. 5	所检项目合格		
70	GX-B1417/22-P-22074	2022. 8. 5	所检项目合格		
71	GX-B1417/22-P-22075	2022. 8. 5	所检项目合格		

72	GX-B1417/22-P-22076	2022. 8. 5	所检项目合格		
73	GX-B1417/22-P-22077	2022. 8. 5	所检项目合格		
74	GX-B1417/22-P-22078	2022. 8. 5	所检项目合格		

75	GX-B1417/22-P-22079	2022. 8. 5	所检项目合格		
76	GX-B1417/22-P-22080	2022. 8. 5	所检项目合格		
77	GX-B1417/22-P-22081	2022. 8. 5	所检项目合格		

78	GX-B1417/22-P-22082	2022. 8. 5	所检项目合格		
79	GX-B1417/22-P-22083	2022. 8. 5	所检项目合格		
80	GX-B1417/22-P-22084	2022. 8. 5	所检项目合格		

81	GX-B1417/22-P-22085	2022. 8. 5	所检项目合格	 A worker wearing a red safety helmet and a blue face mask is seated in the driver's seat of a vehicle, operating the steering wheel. The date '2022/7/21' is visible in the bottom right corner of the photo.
82	GX-B1417/22-P-22086	2022. 8. 5	所检项目合格	 A worker wearing a red safety helmet and a blue face mask is seated in the driver's seat of a vehicle, operating the steering wheel. The date '2022/7/21' is visible in the bottom right corner of the photo.
83	GX-B1417/22-P-22087	2022. 8. 5	所检项目合格	 A worker wearing a red safety helmet and a blue face mask is leaning into the open side door of a vehicle, inspecting equipment. The date '2022/7/21' is visible in the bottom right corner of the photo.

84	GX-B1417/22-P-22088	2022. 8. 5	所检项目合格	
85	GX-B1417/22-P-22089	2022. 8. 5	所检项目合格	
86	GX-B1417/22-P-22090	2022. 8. 5	所检项目合格	

87	GX-B1417/22-P-22091	2022. 8. 5	所检项目合格	
88	GX-B1417/22-P-22092	2022. 8. 5	所检项目合格	
89	GX-B1417/22-P-22093	2022. 8. 5	所检项目合格	

90	GX-B1417/22-P-22094	2022. 8. 5	所检项目合格		
91	GX-B1417/22-P-22095	2022. 8. 5	所检项目合格		
92	GX-B1417/22-P-22096	2022. 8. 5	所检项目合格		

93	GX-B1417/22-P-22097	2022. 8. 5	所检项目合格	 A photograph showing two workers wearing red hard hats and safety glasses. They are standing next to a white truck, looking at something on the side of the vehicle. The date '2022/7/21' is visible in the bottom right corner of the photo.
94	GX-B1417/22-P-22098	2022. 8. 5	所检项目合格	 A photograph of a worker wearing a red hard hat and a blue safety vest. The worker is holding a device and looking at it while standing next to a white truck. The date '2022/7/21' is visible in the bottom right corner of the photo.
95	GX-B1417/22-P-22099	2022. 8. 5	所检项目合格	 A photograph of a worker wearing a red hard hat and safety glasses. The worker is standing next to a forklift in an industrial setting, looking at the machine. The date '2022/7/21' is visible in the bottom right corner of the photo.

96	GX-B1416/22-P-22001	2022. 8. 8	所检项目合格	
97	GX-B1416/22-P-22002	2022. 8. 8	所检项目合格	
98	GX-B1499/21-P-22066	2022. 8. 9	/	

99	GX-B1499/21-P-22067	2022. 8. 9	/			
100	GX-B1499/21-P-22068	2022. 8. 9	/			
101	GX-B1308/21-P-22013	2022. 8. 9	所检项目合格。			
102	GX-B1499/21-P-22069	2022. 8. 9	/			

103	GX-B1499/21-P-22070	2022. 8. 9	/			
104	GX-B1499/21-P-22071	2022. 8. 9	/			
105	GX-B1308/21-P-22014	2022. 8. 9	所检项目合格。			
106	GX-B1559/21-P-22082	2022. 8. 10	所检项目合格			

107	GX-B1559/21-P-22080	2022. 8. 10	所检项目合格	 <p>2022/07/27</p>	
108	GX-B1559/21-P-22081	2022. 8. 10	所检项目合格	 <p>2022/07/27</p>	
109	GX-B1559/22-P-22083	2022. 8. 10	所检项目合格	 <p>2022/07/17</p>	

110	GX-B1559/22-P-22084	2022. 8. 10	所检项目合格	
111	GX-B1559/22-P-22085	2022. 8. 10	所检项目合格	
112	GX-B1559/22-P-22086	2022. 8. 10	所检项目合格	

113	GX-B1559/22-P-22087	2022. 8. 10	所检项目合格		
114	GX-B1559/22-P-22088	2022. 8. 10	所检项目合格		
115	GX-B1559/22-P-22089	2022. 8. 10	所检项目合格		

116	GX-B1559/22-P-22090	2022. 8. 10	所检项目合格		
117	GX-B1559/22-P-22091	2022. 8. 10	所检项目合格		