



序号	报告编号	发布日期	结论	影像资料
57	GX-B1350/21-2-22082	2022/9/7	合格	
58	GX-B1350/21-2-22083	2022/9/7	合格	

59	GX-B1350/21-2-22084	2022/9/7	合格	
60	GX-B1350/21-2-22085	2022/9/7	合格	

61	GX-B1350/21-2-22086	2022/9/7	合格	
62	GX-B1312/20-2-22268~22272	2022/9/7	合格	

63	GX-B1312/20-2-22273~22275	2022/9/7	合格	
64	GX-B1312/20-2-22276~22277	2022/9/7	合格	



65	GX-B1312/20-2-22278~22279	2022/9/7	合格	
66	GX-B1312/20-2-22280~22283	2022/9/7	合格	

67	GX-B1312/20-2-22284~22288	2022/9/7	合格	
68	GX-B1312/20-2-22289~22292	2022/9/7	合格	

69	GX-B1312/20-2-22293~22296	2022/9/7	合格	
70	GX-B1312/20-2-22297~22302	2022/9/7	合格	

71	GX-B1321/20-2-22530~22535	2022/9/7	合格	
72	GX-B1321/20-2-22536~22539	2022/9/7	合格	



73	GX-B1321/20-2-22540~22545	2022/9/7	合格	
74	GX-B1321/20-2-22546~22549	2022/9/7	合格	

75	GX-B1321/20-2-22550~22551	2022/9/7	合格	
76	GX-B1321/20-2-22552~22562	2022/9/7	合格	

77	GX-B1321/20-2-22563~22570	2022/9/7	合格	
78	GX-B1321/20-2-22571~22578	2022/9/7	合格	

79	GX-B1321/20-2-22579~22582	2022/9/7	合格	 <p>2022. 8. 23</p>
80	GX-B1321/20-2-22583~22590	2022/9/7	合格	 <p>2022. 8. 24</p>



81	GX-B1321/20-2-22591~22594	2022/9/7	合格	
82	GX-B1321/20-2-22595~22602	2022/9/7	合格	

83	GX-B1495/20-2-222421~222439	2022. 9. 9	合格	 <p>2022/09/16</p>
84	GX-B1495/20-2-222470~222479	2022. 9. 9	合格	 <p>2022/09/20</p>
85	GX-B1329/21-2-22174~22177	2022/9/8	合格	 <p>2022. 8. 16</p>



86	GX-B1329/21-2-22178~22179	2022/9/8	合格	
87	GX-B1329/21-2-22180~22181	2022/9/8	合格	

88	GX-B1329/21-2-22182~22203	2022/9/8	合格	
89	GX-B1329/21-2-22204~22213	2022/9/8	合格	



90	GX-B1329/21-2-22214~22227	2022/9/8	合格	
91	GX-B1329/21-2-22228~22236	2022/9/8	合格	

92	GX-B1329/21-2-22237~22241	2022/9/8	合格	
93	GX-B1329/21-2-22242~22246	2022/9/8	合格	

94	GX-B1329/21-2-22247~22252	2022/9/8	合格	
95	GX-B1329/21-2-22253~22259	2022/9/8	合格	

96	GX-B1329/21-2-22260~22261	2022/9/8	合格	
97	GX-B1329/21-2-22262	2022/9/8	合格	




98	GX-B1329/21-2-22263	2022/9/8	合格	
99	GX-B1328/20-2-22159	2022. 9. 8	合格	


100	GX-B1350/21-2-22087	2022. 9. 9	合格	    
101	GX-B1495/20-2-222480~222486	2022. 9. 9	合格	

102	GX-B1495/20-2-222487~222495	2022. 9. 9	合格	 <p>2022/08/20</p>
103	GX-B1312/20-2-22368~22376	2022. 9. 9	合格	 <p>2022/08/28</p>
104	GX-B1312/20-2-22377~22390	2022. 9. 9	合格	 <p>2022/09/26</p>

105	GX-B1312/20-2-22391~22392	2022. 9. 9	合格	 2022/08/21
106	GX-B1312/20-2-22394~22396	2022. 9. 9	合格	 2022/08/16
107	GX-B1321/20-2-22603~22610	2022. 9. 9	合格	 2022/08/17






108	GX-B1321/20-2-22611~22618	2022. 9. 9	合格		
109	GX-B1321/20-2-22619~22626	2022. 9. 9	合格		
110	GX-B1321/20-2-22627~22635	2022. 9. 9	合格		




111	GX-B1321/20-2-22636~22643	2022. 9. 9	合格	 <p>2022/08/26</p>
112	GX-B1321/20-2-22644~22652	2022. 9. 9	合格	 <p>2022/08/23</p>
113	GX-B1321/20-2-22653~22658	2022. 9. 9	合格	 <p>2022/08/24</p>

114	GX-B1321/20-2-22659~22666	2022. 9. 9	合格		
115	GX-B1321/20-2-22667~22678	2022. 9. 9	合格		
116	GX-B1321/20-2-22679~22686	2022. 9. 9	合格		

117	GX-B1321/20-2-22692~22700	2022. 9. 9	合格	
118	GX-B1321/20-2-22701~22708	2022. 9. 9	合格	
119	GX-B1312/20-2-22303~22308	2022. 9. 9	合格	

120	GX-B1312/20-2-22309~22314	2022. 9. 9	合格	
121	GX-B1312/20-2-22315~22322	2022. 9. 9	合格	
122	GX-B1312/20-2-22323~22337	2022. 9. 9	合格	

123	GX-B1312/20-2-22338~22351	2022.9.9	合格	 A photograph showing two workers in reflective safety gear and hard hats working at night. They are positioned near a blue container. The ground is dark, and some equipment is visible. A timestamp '2022/08/30' is visible in the bottom right corner of the image.
124	GX-B1312/20-2-22352~22367	2022.9.9	合格	 A photograph showing two workers in reflective safety gear and hard hats working at night. They are positioned near a white container. The ground is dark, and some equipment is visible. A timestamp '2022/08/31' is visible in the bottom right corner of the image.
125	GX-B1312/20-2-22397~22402	2022.9.9	合格	 A photograph showing two workers in a control room or office. One worker is kneeling on the floor, and the other is standing. They are in front of a large control panel with many buttons and screens. A yellow safety line is on the floor. A timestamp '2022/08/30' is visible in the bottom right corner of the image.

126	GX-B1312/20-2-22403~22408	2022.9.9	合格	
127	GX-B1314/21-2-22011~22012	2022.9.9	合格	
128	GX-B1314/21-2-22013~22016	2022.9.9	合格	

129	GX-B1314/21-2-22017~22018	2022. 9. 9	合格	
130	GX-B1495/20-2-221090~221113	2022. 9. 8	合格	
131	GX-B1495/20-2-221294~221301	2022. 9. 8	合格	



132	GX-B1323/21-2-22145~22148	2022.9.9	合格		
133	GX-B1323/21-2-22149~22150	2022.9.9	合格		
134	GX-B1323/21-2-22151~22156	2022.9.9	合格		















































|

























