



| 215 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|-------------|---------|---|
| 216 | GX-B1310/21-C-22047 | 2022. 9. 19 | 符合标准要求。 |  |
| 217 | GX-B1310/21-C-22048 | 2022. 9. 19 | 符合标准要求。 |  |
| 218 | GX-B1548/20-2-22122 | 2022. 9. 20 | 合格 |  |
| 219 | GX-B1548/20-2-22123 | 2022. 9. 20 | 合格 |  |

| | | | | |
|-----|---------------------|-------------|----|---|
| 220 | GX-B1548/20-2-22124 | 2022. 9. 20 | 合格 |  <p>2022/08/16</p> |
| 221 | GX-B1548/20-2-22125 | 2022. 9. 20 | 合格 |  <p>2022/08/16</p> |
| 222 | GX-B1328/20-2-22163 | 2022. 9. 20 | 合格 |  |
| 223 | GX-B1328/20-2-22164 | 2022. 9. 20 | 合格 |  |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 224 | GX-B1495/20-2-222440~ 222454 | 2022/9/21 | 所检项目合格 |  <p>2022/08/29</p> |
| 225 | GX-B1495/20-2-222455~ 222469 | 2022/9/21 | 所检项目合格 |  <p>2022/08/28</p> |

| | | | | |
|-----|---------------------------------|-----------|--------|---|
| 226 | GX-B1495/20-2-222700~ 222714 | 2022/9/21 | 所检项目合格 |  A photograph showing a worker wearing a red hard hat and safety glasses, working on a piece of equipment. The worker is wearing a grey shirt and dark pants. The equipment is white and has a door open. The date '2022/09/21' is visible in the bottom right corner of the photo. |
| 227 | GX-B1495/20-2-222715~ 222727 | 2022/9/21 | 所检项目合格 |  A photograph showing a worker wearing a red hard hat and safety glasses, working on a piece of equipment. The worker is wearing a grey shirt and dark pants. The equipment is white and has a door open. The date '2022/09/21' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|-------------------------------|-----------|--------|--|
| 228 | GX-B1381/20-2-22025 | 2022/9/21 | 所检项目合格 |  A photograph showing a worker in a blue uniform and red helmet kneeling on the floor next to an orange toolbox. The worker is looking towards the camera. The background is a dark, industrial environment with some equipment visible. A timestamp '2022.08.15' is visible in the bottom right corner of the photo. |
| 229 | GX-B1451/20-2-22187~ 22189 | 2022/9/21 | 所检项目合格 |  A photograph showing a worker in a white uniform standing next to a large white electrical cabinet. The worker is looking at the cabinet. The room is brightly lit, and there are yellow safety barriers in the foreground. A timestamp '2022.07.24' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 230 | GX-B1495/20-2-222585~ 222594 | 2022/9/21 | 所检项目合格 |  |
| 231 | GX-B1495/20-2-222728~ 222737 | 2022/9/21 | 所检项目合格 |  |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 232 | GX-B1495/20-2-222738~ 222765 | 2022/9/21 | 所检项目合格 |  |
| 233 | GX-B1495/20-2-222562~ 222584 | 2022/9/21 | 所检项目合格 |  |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 234 | GX-B1495/20-2-222650~ 222662 | 2022/9/21 | 所检项目合格 |  |
| 235 | GX-B1495/20-2-222663~ 222673 | 2022/9/21 | 所检项目合格 |  |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 236 | GX-B1495/20-2-222595~ 222600 | 2022/9/21 | 所检项目合格 |  |
| 237 | GX-B1495/20-2-222601~ 222613 | 2022/9/21 | 所检项目合格 |  |

| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 238 | GX-B1495/20-2-222614~ 222620 | 2022/9/21 | 所检项目合格 |  <p>2022/08/19</p> |
| 239 | GX-B1495/20-2-222621~ 222630 | 2022/9/21 | 所检项目合格 |  <p>2022/08/21</p> |





| | | | | |
|-----|---------------------------------|-----------|--------|--|
| 240 | GX-B1495/20-2-222631~ 222640 | 2022/9/21 | 所检项目合格 |  |
| 241 | GX-B1495/20-2-222641~ 222649 | 2022/9/21 | 所检项目合格 |  |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 242 | GX-B1385/21-2-22055 | 2022/9/22 | 所检项目合格 |  |
| 243 | GX-B1385/21-2-22056 | 2022/9/22 | 所检项目合格 |  |

| | | | | |
|-----|---------------------|-----------|--------|---|
| 244 | GX-B1385/21-2-22057 | 2022/9/22 | 所检项目合格 |  A photograph showing a worker in a red helmet and safety gear using a tool on a structure at night. The worker is illuminated by a bright light source, possibly a headlamp or flashlight. The background is dark, suggesting an outdoor or industrial setting at night. A timestamp '2022/08/20' is visible in the bottom right corner of the image. |
| 245 | GX-B1385/21-2-22058 | 2022/9/22 | 所检项目合格 |  A photograph showing a worker in a red helmet and safety gear at night. The worker is wearing a red jacket and a red helmet. The background is dark, suggesting an outdoor or industrial setting at night. A timestamp '2022/08/20' is visible in the bottom right corner of the image. |

| | | | | |
|-----|---------------------|-----------|--------|---|
| 246 | GX-B1385/21-2-22059 | 2022/9/22 | 所检项目合格 |  <p>A photograph showing a worker wearing a red safety helmet and a dark jacket, working on a large, cylindrical metal structure in a dark, industrial setting. The worker is positioned on the right side of the structure. A timestamp '2022/08/20' is visible in the bottom right corner of the image.</p> |
| 247 | GX-B1385/21-2-22060 | 2022/9/22 | 所检项目合格 |  <p>A photograph showing a worker wearing a red safety helmet and safety gear, working in a dark, confined space. The worker is holding a tool or equipment. The scene is illuminated by bright, focused lights, creating a high-contrast environment. A timestamp '2022/08/20' is visible in the bottom right corner of the image.</p> |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 248 | GX-B1385/21-2-22061 | 2022/9/22 | 所检项目合格 |  <p>2022/08/20</p> |
| 249 | GX-B1328/20-2-22167 | 2022.9.20 | 合格 |  <p>2022/9/20</p> |
| 250 | GX-B1328/20-2-22172 | 2022.9.20 | 合格 |  <p>2022/9/20</p> |

| | | | | |
|-----|---------------------------------|-------------|----|---|
| 251 | GX-B1495/20-2-221450~ 221453 | 2022. 9. 21 | 合格 |  |
| 252 | GX-B1495/20-2-221576~ 221585 | 2022. 9. 21 | 合格 |  |
| 253 | GX-B1495/20-2-221586~ 221595 | 2022. 9. 21 | 合格 |  |
| 254 | GX-B1323/21-2-22180~ 22189 | 2022. 9. 22 | 合格 |  |



| | | | | | |
|-----|-------------------------------|-------------|----|--|--|
| 255 | GX-B1323/21-2-22157~ 22164 | 2022. 9. 22 | 合格 |  | |
| 256 | GX-B1323/21-2-22165~ 22179 | 2022. 9. 22 | 合格 |  | |
| 257 | GX-B1328/20-2-22170 | 2022. 9. 20 | 合格 |  | |

| | | | | |
|-----|---------------------|-------------|----|--|
| 258 | GX-B1328/20-2-22171 | 2022. 9. 20 | 合格 |  |
| 259 | GX-B1328/20-2-22165 | 2022. 9. 20 | 合格 |  |

| | | | | |
|-----|---------------------|-------------|----|---|
| 260 | GX-B1328/20-2-22166 | 2022. 9. 20 | 合格 |  |
| 261 | GX-B1404/20-2-22016 | 2022. 9. 22 | 合格 |  |
| 262 | GX-B1404/20-2-22017 | 2022. 9. 22 | 合格 |  |

| | | | | | | |
|-----|---------------------|-------------|----|--|---|--|
| 263 | GX-B1404/20-2-22018 | 2022. 9. 22 | 合格 | |  | |
| 264 | GX-B1404/20-2-22019 | 2022. 9. 22 | 合格 | |  | |
| 265 | GX-B1404/20-2-22020 | 2022. 9. 22 | 合格 | |  | |

| | | | | |
|-----|---------------------|-------------|----|---|
| 266 | GX-B1404/20-2-22021 | 2022. 9. 22 | 合格 |  |
| 267 | GX-B1404/20-2-22022 | 2022. 9. 22 | 合格 |  |
| 268 | GX-B1404/20-2-22023 | 2022. 9. 22 | 合格 |  |

| | | | | | |
|-----|---------------------|-------------|----|---|--|
| 269 | GX-B1404/20-2-22024 | 2022. 9. 22 | 合格 |  | |
| 270 | GX-B1404/20-2-22025 | 2022. 9. 22 | 合格 |  | |