



序号	报告编号	发布日期	结论	影像资料
1	GX-B1423/20-1-22404	2022/12/1	合格	 A yellow truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '1' visible on its side.
2	GX-B1423/20-1-22405	2022/12/1	合格	 A yellow truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '2' visible on its side.
3	GX-B1423/20-1-22406	2022/12/1	合格	 A yellow truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '3' visible on its side.
4	GX-B1423/20-1-22407	2022/12/1	合格	 A yellow truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '5' visible on its side.

5	GX-B1423/20-1-22408	2022/12/1	合格	 A yellow dump truck with the number '6' on its side. Two workers in blue and grey uniforms and hard hats are standing in front of it. A timestamp '2022.11.22' is visible in the bottom right corner of the photo.
6	GX-B1423/20-1-22409	2022/12/1	合格	 A yellow dump truck parked on a dirt road. Two workers in blue and grey uniforms and hard hats are standing next to it. A timestamp '2022.11.22' is visible in the bottom right corner of the photo.
7	GX-B1423/20-1-22410	2022/12/1	合格	 A yellow dump truck with the number '8' on its side. Two workers in blue and grey uniforms and hard hats are standing in front of it. A timestamp '2022.11.22' is visible in the bottom right corner of the photo.
8	GX-B1423/20-1-22411	2022/12/1	合格	 A yellow dump truck with the number '8' on its side. Two workers in blue and grey uniforms and hard hats are standing in front of it. A timestamp '2022.11.22' is visible in the bottom right corner of the photo.

9	GX-B1423/20-1-22412	2022/12/1	合格	 A yellow MTW 70 truck is shown from a front-quarter view. Two workers in safety gear are standing in front of the truck. A date stamp '2022.12' is visible in the bottom right corner of the photo.
10	GX-B1423/20-1-22413	2022/12/1	合格	 A yellow MTW 11 truck is shown from a front-quarter view. Two workers in safety gear are standing in front of the truck. A date stamp '2022.12' is visible in the bottom right corner of the photo.