

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-3-22156	2022. 12. 1	符合标准要求	 <p>2022.11.8</p>

2	GX-B1427/21-3-22053	2022. 12. 1	符合标准要求	
3	GX-B1416/22-3-22061	2022. 12. 1	合格	

4	GX-B1328/20-3-22197	2022. 12. 1	合格	
5	GX-B1328/20-3-22198	2022. 12. 1	合格	

6	GX-B1328/20-3-22202	2022.12.1	合格	
7	GX-B1328/20-3-22203	2022.12.1	合格	

8	GX-B1328/20-3-22204	2022. 12. 1	合格	
9	GX-B1306/21-3-22047	2022年12月2日	所检项目合格	
10	GX-B1306/21-3-22048	2022年12月2日	所检项目合格	

11	GX-B1306/21-3-22049	2022年12月2日	所检项目合格	
12	GX-B1306/21-3-22050	2022年12月2日	所检项目合格	
13	GX-B1306/21-3-22051	2022年12月2日	所检项目合格	

14	GX-B1306/21-3-22052	2022年12月2日	所检项目合格	
15	GX-B1300/20-3-22007	2022年12月2日	合格	
16	GX-B1301/21-3-22012	2022年12月2日	合格	

17	GX-B1301/21-3-22013	2022年12月2日	合格	
18	GX-B1302/21-3-22010	2022年12月2日	合格	

19	GX-B1383/21-3-22003	2022. 12. 6	所检项目合格	
20	GX-B1383/21-3-22004	2022. 12. 6	所检项目合格	

21	GX-B1383/21-3-22005	2022. 12. 6	所检项目合格	
22	GX-B1383/21-3-22006	2022. 12. 6	所检项目合格	

23	GX-B1517/20-3-22036	2022. 12. 5	综合判定合格	
----	---------------------	-------------	--------	-------------------------------------------------------------------------------------

24	GX-B1517/20-3-22037	2022. 12. 5	综合判定合格	
----	---------------------	-------------	--------	-------------------------------------------------------------------------------------

25	GX-B1517/20-3-22038	2022. 12. 5	综合判定合格	
----	---------------------	-------------	--------	-------------------------------------------------------------------------------------

26	GX-B1517/20-3-22039	2022. 12. 5	综合判定合格	
27	GX-B1517/20-3-22040	2022. 12. 5	综合判定合格	

28	GX-B1517/20-3-22041	2022. 12. 5	综合判定合格	
29	GX-B1517/20-3-22042	2022. 12. 5	综合判定合格	

30	GX-B1517/20-3-22043	2022. 12. 5	综合判定合格	 A photograph showing two workers in a tunnel. They are wearing red hard hats and high-visibility vests. The tunnel is dimly lit, with a bright light source on the left. A date stamp '2022.11.14' is visible in the bottom right corner.
31	GX-B1517/20-3-22044	2022. 12. 5	综合判定合格	 A photograph showing two workers in a tunnel. One worker is standing on the left, and another is kneeling on the floor on the right. The tunnel walls are white and blue. A date stamp '2022.11.14' is visible in the bottom right corner.

32	GX-B1354/20-3-22017	2022. 12. 6	电网接地电容电流符合规定	
33	GX-B1495/20-3-224009-224010	2022年12月7日	所检项目合格	

34	GX-B1310/21-3-22157	2022年12月2日	符合标准要求	 <p>2022.11.12</p>
35	GX-B1310/21-3-22158	2022年12月2日	符合标准要求	 <p>2022.11.13</p>
36	GX-B1310/21-3-22159	2022年12月2日	符合标准要求	 <p>OPPO Reno5 Pro 5G 2022年11月11日</p>

37	GX-B1310/21-3-22160	2022年12月2日	符合标准要求		
38	GX-B1427/21-3-22054	2022年12月2日	符合标准要求		
39	GX-B1427/21-3-22055	2022年12月2日	符合标准要求		