

序号	报告编号	发布日期	结论	影像资料
458	GX-B1306/21-Y-23009	2023年2月9日	所检项目合格	
459	GX-B1306/21-Y-23010	2023年2月9日	所检项目合格	

460	GX-B1306/21-Y-23011	2023年2月9日	所检项目合格	
461	GX-B1306/21-Y-23012	2023年2月9日	所检项目合格	

462	GX-B1350/21-Y-23001	2023年2月7日	所检项目合格	
463	GX-B1300/20-Y-23001	2023年2月8日	合格	
464	GX-B1310/21-Y-23005	2023年2月10日	符合标准要求	

465	GX-B1310/21-Y-23006	2023年2月10日	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷	
466	GX-B1428/21-Y-23007	2023年2月10日	符合标准要求	
467	GX-B1310/21-Y-23007	2023年2月10日	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷	

468	GX-B1428/21-Y-23008	2023年2月10日	符合标准要求	 <p>2023/1/15</p>
469	GX-B1310/21-Y-2308	2023年2月10日	未发现超过 $\Phi 3\text{mm}$ 当量直径的缺陷	 <p>2023/1/15</p>
470	GX-B1423/20-Y-23520	2023年2月11日	综合判定：合格	 <p>2023/1/19</p>

471	GX-B1423/20-Y-23521	2023年2月11日	综合判定：合格	 A yellow MTBE truck is shown from a front-three-quarter view. Two workers in safety gear are standing in front of the truck on a dark, muddy surface. A yellow timestamp '2023/1/19' is visible in the bottom right corner of the photo.
472	GX-B1423/20-Y-23522	2023年2月11日	综合判定：合格	 A yellow MTBE truck is shown from a front-three-quarter view. Two workers in safety gear are standing in front of the truck on a dark, muddy surface. A yellow timestamp '2023/1/19' is visible in the bottom right corner of the photo.
473	GX-B1423/20-Y-23523	2023年2月11日	综合判定：合格	 A yellow MTBE truck is shown from a side view. The truck's bed is raised. Two workers in safety gear are standing in front of the truck on a dark, muddy surface. A yellow timestamp '2023/1/19' is visible in the bottom right corner of the photo.

474	GX-B1423/20-Y-23524	2023年2月11日	综合判定：合格	 A yellow MT880 truck is parked on a snowy surface. Two people are standing in front of the truck. The truck has 'MT880' and 'CUMMINS' visible on its front. A yellow timestamp '2023/1/19' is in the bottom right corner.
475	GX-B1423/20-Y-23525	2023年2月11日	综合判定：合格	 A yellow MT880 truck is parked on a dark, muddy surface. A person is standing next to the truck. The truck has 'MT880' visible on its front. A yellow timestamp '2023/1/19' is in the bottom right corner.
476	GX-B1423/20-Y-23526	2023年2月11日	综合判定：合格	 A yellow MT880 truck with its bed raised is parked on a snowy surface. A person is standing next to the truck. The truck has 'MT880' and 'CUMMINS' visible on its side. A yellow timestamp '2023/1/19' is in the bottom right corner.

477	GX-B1385/21-Y-22055	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---



478	GX-B1385/21-Y-22056	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---


479	GX-B1385/21-Y-22057	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

480	GX-B1385/21-Y-22058	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

481	GX-B1385/21-Y-22059	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

482	GX-B1385/21-Y-22062	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

483	GX-B1385/21-Y-22063	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

484	GX-B1385/21-Y-22064	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

485	GX-B1385/21-Y-22065	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---



486	GX-B1385/21-Y-22066	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

487	GX-B1385/21-Y-22067	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

488	GX-B1385/21-Y-22068	2023年2月5日	所检项目合格	
-----	---------------------	-----------	--------	---

489	GX-B1385/21-Y-22069	2023年2月5日	所检项目合格	 <p>A photograph showing a worker in a white uniform and cap inspecting equipment in a confined space. The worker is holding a device, possibly a camera or a measuring tool. The equipment is yellow and white. A date stamp '2023/2/22' is visible in the bottom right corner of the photo.</p>
490	GX-B1415/22-Y-23001	2023年2月9日	综合判定：合格。	 <p>A photograph showing two workers in a tunnel or underground setting. One worker is wearing a yellow jacket and the other is wearing a dark jacket. They are standing on a concrete floor. A date stamp '2023/2/22' is visible in the bottom left corner of the photo.</p>

491	GX-B1499/21-Y-23014	2023年2月9日	所检项目合格。	
492	GX-B1499/21-Y-23015	2023年2月9日	所检项目合格。	
493	GX-B1499/21-Y-23016	2023年2月9日	所检项目合格。	

494	GX-B1308/21-Y-23003	2023年2月9日	所检项目合格。	
495	GX-B1423/20-Y-23453	2023年2月10日	综合判定：合格	
496	GX-B1423/20-Y-23454	2023年2月10日	综合判定：合格	


497	GX-B1423/20-Y-23455	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '079' on its side, parked on a snowy field. Two people are standing in front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the photo.
498	GX-B1423/20-Y-23456	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '032' on its side, parked on a snowy field. Two people are standing in front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the photo.
499	GX-B1423/20-Y-23457	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '031' on its side, parked on a snowy field. Two people are standing in front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the photo.

500	GX-B1423/20-Y-23458	2023年2月10日	综合判定：合格	 A yellow dump truck with the number 500 on its side, parked on a snowy surface. A person is standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.
501	GX-B1423/20-Y-23459	2023年2月10日	综合判定：合格	 A yellow dump truck with the number 501 on its side, parked on a snowy surface. Two people are standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.
502	GX-B1423/20-Y-23460	2023年2月10日	综合判定：合格	 A yellow dump truck with the number 502 on its side, parked on a snowy surface. Two people are standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.




503	GX-B1423/20-Y-23461	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '081' on its side. Two people are standing in front of it. A yellow timestamp '2023/1/17' is in the bottom right corner.
504	GX-B1423/20-Y-23462	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '081' on its side. Two people are standing in front of it. A yellow timestamp '2023/1/17' is in the bottom right corner.
505	GX-B1423/20-Y-23463	2023年2月10日	综合判定：合格	 A yellow dump truck with the number '082' on its side. Two people are standing in front of it. A yellow timestamp '2023/1/17' is in the bottom right corner.

506	GX-B1423/20-Y-23464	2023年2月10日	综合判定：合格	
507	GX-B1423/20-Y-23465	2023年2月10日	综合判定：合格	
508	GX-B1423/20-Y-23466	2023年2月10日	综合判定：合格	

509	GX-B1423/20-Y-23467	2023年2月10日	综合判定：合格	
510	GX-B1423/20-Y-23468	2023年2月10日	综合判定：合格	
511	GX-B1423/20-Y-23469	2023年2月10日	综合判定：合格	

512	GX-B1423/20-Y-23470	2023年2月9日	综合判定：合格	 A yellow dump truck with the number '050' on its side, parked on a snowy surface. Two people are standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.
513	GX-B1423/20-Y-23471	2023年2月9日	综合判定：合格	 A yellow dump truck with the number '078' on its side, parked on a snowy surface. Two people are standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.
514	GX-B1423/20-Y-23472	2023年2月9日	综合判定：合格	 A yellow dump truck with the number '023' on its side, parked on a snowy surface. Two people are standing near the front of the truck. A yellow timestamp '2023/1/17' is visible in the bottom right corner of the image.

515	GX-B1423/20-Y-23473	2023年2月9日	综合判定：合格	
516	GX-B1423/20-Y-23474	2023年2月9日	综合判定：合格	
517	GX-B1423/20-Y-23475	2023年2月9日	综合判定：合格	

518	GX-B1423/20-Y-23476	2023年2月9日	综合判定：合格	 A photograph showing a person in a military-style uniform sitting in the driver's seat of a vehicle, operating the controls. The person is wearing a helmet and a camouflage jacket. The vehicle's interior, including the steering wheel and dashboard, is visible. A yellow timestamp '2023/1/17' is present in the bottom right corner of the image.
519	GX-B1423/20-Y-23477	2023年2月9日	综合判定：合格	 A photograph showing a person in a military-style uniform sitting in the driver's seat of a vehicle, operating the controls. The person is wearing a helmet and a camouflage jacket. The vehicle's interior, including the steering wheel and dashboard, is visible. A yellow timestamp '2023/1/17' is present in the bottom right corner of the image.
520	GX-B1423/20-Y-23478	2023年2月9日	综合判定：合格	 A photograph showing a person in a military-style uniform sitting in the driver's seat of a vehicle, operating the controls. The person is wearing a helmet and a camouflage jacket. The vehicle's interior, including the steering wheel and dashboard, is visible. A yellow timestamp '2023/1/17' is present in the bottom right corner of the image.

521	GX-B1423/20-Y-23479	2023年2月9日	综合判定：合格	
522	GX-B1423/20-Y-23480	2023年2月9日	综合判定：合格	
523	GX-B1423/20-Y-23481	2023年2月9日	综合判定：合格	

524	GX-B1423/20-Y-23482	2023年2月9日	综合判定：合格	 A close-up photograph of a person wearing a dark jacket and a cap, sitting in the driver's seat of a yellow truck. The person is looking towards the right side of the frame. The interior of the cab is visible, including the steering wheel and dashboard. A yellow timestamp '2023/11/17' is visible in the bottom right corner of the image.
525	GX-B1423/20-Y-23483	2023年2月9日	综合判定：合格	 A close-up photograph of a person wearing a dark jacket and a cap, sitting in the driver's seat of a yellow truck. The person is looking towards the right side of the frame. The interior of the cab is visible, including the steering wheel and dashboard. A yellow timestamp '2023/11/17' is visible in the bottom right corner of the image.
526	GX-B1423/20-Y-23484	2023年2月9日	综合判定：合格	 A photograph of a large yellow dump truck parked on a snowy or icy surface. Two people are standing in front of the truck, one in a dark jacket and one in a patterned jacket. The truck has '陕汽重卡' (Shaanxi Heavy Truck) written on its side. A yellow timestamp '2023/11/18' is visible in the bottom right corner of the image.



527	GX-B1423/20-Y-23485	2023年2月9日	综合判定：合格	 A photograph showing a person wearing a grey beanie, a camouflage jacket, and dark pants, sitting in the driver's seat of a vehicle. The person is looking towards the camera. The vehicle's interior, including the steering wheel and dashboard, is visible. A yellow timestamp '2023-11-16' is in the bottom right corner.
528	GX-B1423/20-Y-23486	2023年2月9日	综合判定：合格	 A photograph showing a person wearing a grey beanie, a camouflage jacket, and dark pants, sitting in the driver's seat of a vehicle. The person is looking towards the camera. The vehicle's interior, including the steering wheel and dashboard, is visible. A yellow timestamp '2023-11-16' is in the bottom right corner.