

序号	报告编号	发布日期	结论	影像资料
747	GX-B1306/21-Y-23013	2023年2月13日	所检项目合格	
748	GX-B1306/21-Y-23014	2023年2月13日	所检项目合格	


749	GX-B1306/21-Y-23015	2023年2月13日	所检项目合格	
750	GX-B1306/21-Y-23016	2023年2月13日	所检项目合格	

751	GX-B1306/21-Y-23017	2023年2月13日	所检项目合格	
752	GX-B1306/21-Y-23018	2023年2月13日	所检项目合格	

753	GX-B1306/21-Y-23019	2023年2月13日	所检项目合格	
754	GX-B1416/22-Y-23004	2023年2月14日	综合判定：合格	


755	GX-B1499/21-Y-23017	2023年2月15日	所检项目合格。	
756	GX-B1499/21-Y-23018	2023年2月15日	所检项目合格。	

757	GX-B1499/21-Y-23019	2023年2月15日	所检项目合格。	
758	GX-B1499/21-Y-23020	2023年2月15日	所检项目合格。	

759	GX-B1416/22-Y-23005	2023年2月15日	综合判定：合格。	
760	GX-B1321/20-Y-23006~23007	2023年2月15日	所检项目合格。	

761	GX-B1312/20-Y-23032~23033	2023年2月15日	所检项目合格。	
762	GX-B1499/21-Y-23021	2023年2月15日	所检项目合格。	



763	GX-B1499/21-Y-23022	2023年2月15日	所检项目合格。	
764	GX-B1499/21-Y-23023	2023年2月15日	所检项目合格。	

765	GX-B1308/21-Y-23004	2023年2月15日	所检项目合格。	 <p>2023/2/11</p>
766	GX-B1495/20-Y-23091~23109	2023年2月15日	所检项目合格。	 <p>2023/2/11</p>

767	GX-B1323/21-Y-23001~23003	2023年2月15日	所检项目合格。	
768	GX-B1339/21-Y-23001	2023年2月15日	所检项目合格	

769	GX-B1339/21-Y-23002	2023年2月15日	所检项目合格	
770	GX-B1339/21-Y-23003	2023年2月15日	所检项目合格	

771	GX-B1339/21-Y-23004	2023年2月15日	所检项目合格	 A worker in a red uniform and helmet is inspecting a large green industrial machine in a factory setting. The machine has a blue base and a red component. A date stamp '2023/2/11' is visible in the bottom right corner of the photo.
772	GX-B1339/21-Y-23005	2023年2月15日	所检项目合格	 A worker in a red uniform and helmet is working on a large green industrial machine, possibly performing maintenance or inspection. The worker is using a tool on a pipe or component. A date stamp '2023/2/11' is visible in the bottom right corner of the photo.

773	GX-B1339/21-Y-23006	2023年2月15日	所检项目合格	 <p>2023/2/11</p>
774	GX-B1380/20-Y-23001	2023年2月17日	所检项目合格。	 <p>2023/2/9</p>

775	GX-B1380/20-Y-23002	2023年2月17日	所检项目合格。	 A photograph showing two workers in grey work clothes and red hard hats. They are standing on a narrow platform or walkway, inspecting a large, complex piece of machinery. The environment appears to be an industrial or mining setting. A yellow timestamp '2023/2/9' is visible in the bottom right corner of the photo.
776	GX-B1515/22-Y-23001	2023年2月17日	所检项目合格。	 A photograph showing three workers in red work clothes and headlamps. They are in a dark, underground environment, likely a mine. They are gathered around a large, blue piece of machinery, possibly a conveyor or a large container, and appear to be inspecting it. The scene is dimly lit, with the primary light source being the workers' headlamps. A yellow timestamp '2023/2/9' is visible in the bottom right corner of the photo.

777	GX-B1515/22-Y-23002	2023年2月17日	所检项目合格。	
778	GX-B1515/22-Y-23003	2023年2月17日	所检项目合格。	



779	GX-B1515/22-Y-23004	2023年2月17日	所检项目合格。	 A photograph showing two workers in red safety suits and helmets with headlamps. They are in a dark, industrial setting, possibly a mine or tunnel. One worker is kneeling and looking at something on the ground, while the other is standing nearby. A date stamp '2023/2/9' is visible in the bottom right corner of the image.
780	GX-B1515/22-Y-23005	2023年2月17日	所检项目合格。	 A photograph showing two workers in red safety suits and helmets with headlamps. They are in a dark, industrial setting. One worker is standing and looking at a piece of equipment with a screen, while the other is standing next to it. A date stamp '2023/2/9' is visible in the bottom right corner of the image.

781	GX-B1517/20-Y-23002	2023年2月17日	综合判定：合格。	
782	GX-B1517/20-Y-23003	2023年2月17日	综合判定：合格。	

783	GX-B1517/20-Y-23004	2023年2月17日	综合判定：合格。	 <p>A photograph showing a person wearing a red hard hat and a grey jacket standing next to a red and green container on a track. The container has the number '2' on it. The background shows an industrial site with blue buildings. A yellow timestamp '2023/2/10' is visible in the bottom right corner of the photo.</p>
784	GX-B1517/20-Y-23005	2023年2月17日	综合判定：合格。	 <p>A photograph showing a person wearing a red hard hat and a grey jacket standing next to a green container on a track. The container is on an orange vehicle. The background shows an industrial site with blue buildings and a clear blue sky. A yellow timestamp '2023/2/10' is visible in the bottom right corner of the photo.</p>

785	GX-B1517/20-Y-23006	2023年2月17日	综合判定：合格。	 <p>A photograph showing a worker in a red protective suit and red helmet standing next to a red industrial vehicle. The worker is wearing a red jacket with reflective stripes and red pants. The vehicle is a small, red, tracked or wheeled machine. The background shows an industrial setting with buildings. A yellow timestamp '2023/2/10' is visible in the bottom right corner of the photo.</p>
786	GX-B1517/20-Y-23007	2023年2月17日	综合判定：合格。	 <p>A photograph showing a worker in a white jacket and red helmet standing next to a red industrial vehicle. The worker is wearing a white jacket and dark pants. The vehicle is a small, red, tracked or wheeled machine. The background shows an industrial setting with buildings. A yellow timestamp '2023/2/10' is visible in the bottom right corner of the photo.</p>

787	GX-B1517/20-Y-23008	2023年2月17日	综合判定：合格。	
788	GX-B1517/20-Y-23009	2023年2月17日	综合判定：合格。	