

序号	报告编号	发布日期	结论	影像资料
18	GX-B1521/20-Y-23026	2023年3月10日	依据GB/T9139-2018 GB/T7586-2018 ,所检项目 合格	 A photograph showing a worker wearing a red safety helmet and a grey uniform, seated inside the cab of a piece of heavy machinery. The worker is looking down at a device in their hands. The date '2023/2/19' is visible in the bottom right corner of the image.
19	GX-B1539/20-Y-23004	2023年3月10日	所检项目合格	 A photograph showing a worker wearing a red safety helmet and a grey uniform, seated in the driver's seat of a piece of machinery. The worker is looking towards the right. The date '2023/2/19' is visible in the bottom right corner of the image.

20	GX-B1423/20-Y-23530	2023年3月10日	综合判定：合格	 A photograph showing a worker in a red hard hat and grey work uniform sitting in the operator's seat of a yellow excavator. The worker is looking towards the camera. The background shows a construction site with a yellow building. A yellow timestamp '2023/2/10' is visible in the bottom right corner of the photo.
21	GX-B1520/20-Y-23009	2023年3月10日	综合判定：合格。	 A photograph showing two workers in red hard hats and grey work uniforms standing next to a yellow excavator at a construction site. One worker is holding a clipboard and looking at it, while the other is looking towards the camera. The background shows a large rock face. A yellow timestamp '2023/2/20' is visible in the bottom left corner of the photo.

22	GX-B1520/20-Y-23010	2023年3月10日	综合判定：合格。	
23	GX-B1522/20-Y-23001	2023年3月10日	所检项目合格。	

24	GX-B1522/20-Y-23002	2023年3月10日	所检项目合格。	
25	GX-B1329/21-Y-23001~23008	2023年3月10日	所检项目合格	

26	GX-B1499/21-Y-23024	2023年3月10日	实测流量为119.3m ³ /h	
27	GX-B1499/21-Y-23025	2023年3月10日	实测流量为122.3m ³ /h	

28	GX-B1499/21-Y-23026	2023年3月10日	实测流量为121.8m ³ /h	 <p>A photograph showing a worker in a grey uniform and red helmet standing next to a yellow pipe in an outdoor industrial setting. The worker is holding a device, possibly a flow meter or sensor, connected to the pipe. A blue safety fence is visible in the foreground. The date stamp '2023/2/15' is visible in the bottom right corner of the image.</p>
29	GX-B1312/20-Y-23034~23035	2023年3月9日	所检项目合格	 <p>A photograph showing a worker in a blue jacket and white pants working on a piece of equipment inside a room. The worker is holding a device, possibly a flow meter or sensor, connected to the equipment. A yellow container is visible on the floor. A red bucket is hanging on the wall. The date stamp '2023/2/15' is visible in the bottom right corner of the image.</p>

30	GX-B1350/21-Y-23002	2023年3月9日	所检项目合格	 <p>A photograph showing a person in a dark jacket and light pants crouching on a concrete floor, inspecting a small area. A red fire extinguisher is visible on the right. The date stamp '2023/2/15' is in the bottom right corner.</p>
31	GX-B1539/22-Y-23001	2023年3月9日	所检项目合格	 <p>A photograph of two men standing in front of a yellow wheel loader. The man on the left is wearing a dark jacket, and the man on the right is wearing a light-colored uniform and a red hard hat. The loader has 'L955F' and '山推重工' (Sany Heavy Industry) visible. The date stamp '2023/2/15' is in the bottom right corner.</p>

32	GX-B1539/22-Y-23002	2023年3月9日	所检项目合格	
33	GX-B1539/22-Y-23003	2023年3月9日	所检项目合格	

34	GX-B1423/20-Y-23528	2023年3月10日	综合判定：合格	
35	GX-B1423/20-Y-23529	2023年3月10日	综合判定：合格	

36	GX-B1423/20-Y-23535	2023年3月10日	综合判定：合格	
37	GX-B1423/20-Y-23536	2023年3月10日	综合判定：合格	

38	GX-B1423/20-Y-23537	2023年3月10日	综合判定：合格	
39	GX-B1521/20-Y-23028	2023年3月10日	依据GB/T9139-2018 GB/T7586-2018 ,所检项目 合格	

40	GX-B1521/20-Y-23027	2023年3月10日	依据GB/T9139-2018 GB/T7586-2018 ,所检项目 合格	
41	GX-B1539/20-Y-23005	2023年3月10日	所检项目合格	

42	GX-B1539/20-Y-23006	2023年3月10日	所检项目合格	
43	GX-B1539/22-Y-23007	2023年3月13日	所检项目合格。	

44	GX-B1539/22-Y-23008	2023年3月13日	所检项目合格。	
45	GX-B1521/20-Y-23029	2023年3月13日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》 》，所检项目合格。	

46	GX-B1521/20-Y-23030	2023年3月13日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
47	GX-B1521/20-Y-23031	2023年3月13日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》</p> <p>GB/ T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

48	GX-B1306/21-Y-23020	2023年3月13日	所检项目合格。	 A worker wearing a white protective suit and a red hard hat is inspecting a large, grey, cylindrical industrial component. The worker is leaning over the component, and a yellow date stamp '2023/2/17' is visible in the bottom right corner of the photo.
49	GX-B1306/21-Y-23021	2023年3月13日	所检项目合格。	 A worker wearing a white protective suit and a red hard hat is inspecting a large, grey, cylindrical industrial component. The component has a large, white, hand-painted number '8' on its side. The worker is leaning over the component, and a yellow date stamp '2023/2/17' is visible in the bottom right corner of the photo.

50	GX-B1306/21-Y-23022	2023年3月13日	所检项目合格。	
51	GX-B1306/21-Y-23023	2023年3月13日	所检项目合格。	

52	GX-B1306/21-Y-23024	2023年3月13日	所检项目合格。	
53	GX-B1306/21-Y-23025	2023年3月13日	所检项目合格。	

54	GX-B1306/21-Y-23026	2023年3月13日	所检项目合格。	 A photograph showing a worker in a grey uniform and red helmet inspecting a blue tank on a vehicle. The worker is holding a blue folder. The date stamp in the bottom right corner of the photo is 2023/2/18.
55	GX-B1306/21-Y-23027	2023年3月13日	所检项目合格。	 A photograph showing a worker in a grey uniform and red helmet inspecting a mechanical component on a vehicle. The worker is holding a blue folder. The date stamp in the bottom right corner of the photo is 2023/2/18.

56	GX-B1306/21-Y-23028	2023年3月13日	所检项目合格。	 A worker wearing a grey uniform and a red hard hat is inspecting a blue piece of machinery. The worker is holding a clipboard and a pen. The machinery has a yellow date stamp in the bottom right corner that reads "2023/2/18".
57	GX-B1306/21-Y-23029	2023年3月13日	所检项目合格。	 A worker wearing a grey uniform and a red hard hat is inspecting a blue piece of machinery. The worker is holding a clipboard and a pen. The machinery has a yellow date stamp in the bottom right corner that reads "2023/2/18".

58	GX-B1306/21-Y-23030	2023年3月13日	所检项目合格。	
59	GX-B1522/20-Y-23011	2023年3月13日	所检项目合格。	



60	GX-B1522/20-Y-23012	2023年3月13日	所检项目合格。	
61	GX-B1522/20-Y-23013	2023年3月13日	所检项目合格。	

62	GX-B1522/20-Y-23014	2023年3月13日	所检项目合格。	
63	GX-B1522/20-Y-23015	2023年3月13日	所检项目合格。	

64	GX-B1522/20-Y-23016	2023年3月13日	所检项目合格。	
65	GX-B1522/20-Y-23017	2023年3月13日	所检项目合格。	

66	GX-B1522/20-Y-23018	2023年3月13日	所检项目合格。	
67	GX-B1522/20-Y-23019	2023年3月13日	所检项目合格。	

68	GX-B1522/20-Y-23020	2023年3月13日	所检项目合格。	
69	GX-B1522/20-Y-23021	2023年3月13日	所检项目合格。	

70	GX-B1522/20-Y-23022	2023年3月13日	所检项目合格。	 A worker in a white uniform and red helmet is inspecting a piece of heavy machinery, possibly a drill or pump, in an industrial setting. The worker is holding a blue folder or clipboard. The machinery is orange and grey. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the photo.
71	GX-B1522/20-Y-23023	2023年3月13日	所检项目合格。	 A worker in a white uniform and red helmet is inspecting a large piece of machinery, possibly a conveyor or pump, in an industrial setting. The machinery is blue and grey, with the number '20' visible on its side. The worker is holding a white folder or clipboard. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the photo.

72	GX-B1522/20-Y-23024	2023年3月13日	所检项目合格。	
73	GX-B1522/20-Y-23025	2023年3月13日	所检项目合格。	