

序号	报告编号	发布日期	结论	影像资料
963	GX-B1328/20-Y-23034	2023/3/29	所检项目合格	
964	GX-B1328/20-Y-23035	2023/3/29	所检项目合格	
965	GX-B1328/20-Y-23036	2023/3/29	所检项目合格	
966	GX-B1328/20-Y-23037	2023/3/29	所检项目合格	

967	GX-B1328/20-Y-23038	2023/3/29	所检项目合格	
968	GX-B1539/22-Y-23021	2023年3月28日	所检项目合格。	
969	GX-B1539/22-Y-23022	2023年3月28日	所检项目合格。	

970	GX-B1312/20-Y-23078~23079	2023年3月29日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>A worker in a white uniform and red helmet is working on a red electrical transformer inside a cabinet. The worker is using a tool to adjust or inspect the transformer. A laptop and other equipment are visible on the floor in front of the cabinet.</p>
971	GX-B1312/20-Y-23080~23081	2023年3月29日	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>Two workers in white uniforms and red helmets are working on a red electrical transformer inside a cabinet. One worker is kneeling and working on the transformer, while the other is standing and holding a document. A laptop and other equipment are visible on the floor in front of the cabinet.</p>

972	GX-B1312/20-Y-23082~23083	2023年3月29日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
973	GX-B1312/20-Y-23084~23085	2023年3月29日	本次共检电力变压器2台，2台电力变压器所检项目合格。	

974	GX-B1312/20-Y-23086	2023年3月29日	所检项目合格。 。	
975	GX-B1312/20-Y-23087~23088	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	

976	GX-B1312/20-Y-23089~23090	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	 A photograph showing a worker in a red hard hat and grey work clothes standing in an electrical room. The worker is positioned next to two large, red cylindrical electrical transformers. The room has various colored pipes (red, yellow, green) and electrical equipment. A yellow date stamp '2023-3-29' is visible in the bottom right corner of the photo.
977	GX-B1312/20-Y-23091~23092	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	 A photograph showing a worker in a red hard hat and grey work clothes kneeling on the floor in an electrical room. The worker is focused on a yellow electrical control box. In the background, two large red cylindrical electrical transformers are visible. The room contains various electrical components and pipes. A yellow date stamp '2023-3-29' is visible in the bottom right corner of the photo.

978	GX-B1312/20-Y-23093~23094	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	
979	GX-B1312/20-Y-23095~23096	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	

980	GX-B1312/20-Y-23097	2023年3月29日	所检项目合格。 。	
981	GX-B1312/20-Y-23098~23099	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	

982	GX-B1312/20-Y-23100~23101	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	
983	GX-B1312/20-Y-23102~23103	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	

984	GX-B1312/20-Y-23104~23105	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	
985	GX-B1312/20-Y-23106	2023年3月29日	所检项目合格 。	

986	GX-B1312/20-Y-23107~23108	2023年3月29日	本次共检电力 变压器2台，2台 电力变压器所检 项目合格。	
987	GX-B1312/20-Y-23109	2023年3月29日	所检项目合格 。	


988	GX-B1312/20-Y-23110	2023年3月29日	所检项目合格。 。	
989	GX-B1312/20-Y-23111	2023年3月29日	所检项目合格。 。	

990	GX-B1312/20-Y-23112	2023年3月29日	所检项目合格。 。	
991	GX-B1312/20-Y-23113	2023年3月29日	所检项目合格。 。	

992	GX-B1312/20-Y-23114	2023年3月29日	所检项目合格。 。	
993	GX-B1312/20-Y-23115	2023年3月29日	所检项目合格。 。	

994	GX-B1312/20-Y-23116	2023年3月29日	所检项目合格。 。	
995	GX-B1312/20-Y-23117	2023年3月29日	所检项目合格。 。	


996	GX-B1312/20-Y-23118	2023年3月29日	所检项目合格。 。	
997	GX-B1312/20-Y-23119	2023年3月29日	所检项目合格。 。	

998	GX-B1312/20-Y-23120~23121	2023年3月29日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
999	GX-B1385/21-Y-23038	2023年3月28日	除未装设制动装置外，其余所检项目合格	

1000	GX-B1385/21-Y-23045	2023年3月28日	所检项目合格	
1001	GX-B1385/21-Y-23049	2023年3月28日	除未装设制动装置外，其余所检项目合格	

1002	GX-B1385/21-Y-23052	2023年3月28日	除该带式输送机未装设防撕裂保护装置、跑偏保护装置、驱动滚筒防滑装置、堆煤保护装置、烟雾保护装置、温度与自动洒水装置和张紧力下降保护外，其余所检项目合格。	 <p>2023/3/4</p>
1003	GX-B1385/21-Y-23053	2023年3月28日	除该带式输送机未装设防撕裂保护装置、跑偏保护装置、驱动滚筒防滑装置、堆煤保护装置、烟雾保护装置、温度与自动洒水装置和张紧力下降保护外，其余所检项目合格。	 <p>2023/3/4</p>

1004	GX-B1385/21-Y-23055	2023年3月28日	除该带式输送机未装设防撕裂保护装置、跑偏保护装置、驱动滚筒防滑装置、堆煤保护装置、烟雾保护装置、温度与自动洒水装置和张紧力下降保护外，其余所检项目合格。	
1005	GX-B1385/21-Y-23056	2023年3月28日	除该带式输送机未装设防撕裂保护装置、跑偏保护装置、驱动滚筒防滑装置、堆煤保护装置、烟雾保护装置、温度与自动洒水装置和张紧力下降保护外，其余所检项目合格。	

1006	GX-B1385/21-Y-23060	2023年3月28日	<p>除该带式输送机未装设防撕裂保护装置、跑偏保护装置、驱动滚筒防滑装置、堆煤保护装置、烟雾保护装置、温度与自动洒水装置和张紧力下降保护外，其余所检项目合格。</p>	 A photograph showing a worker in a red hard hat and safety harness working on a large industrial machine, likely a conveyor belt component. The worker is wearing a grey jacket and is focused on the task. The machine has a blue-painted metal surface. A yellow timestamp '2023/3/28' is visible in the bottom right corner of the image.
------	---------------------	------------	---	--