





序号	报告编号	发布日期	结论	影像资料
224	GX-B1380/20-3-23002	2023. 4. 22	所检项目合格	


225	GX-B1380/20-3-23003	2023. 4. 22	所检项目合格		
226	GX-B1380/20-3-23004	2023. 4. 22	所检项目合格		

227	GX-B1380/20-3-23005	2023. 4. 22	所检项目 合格			
228	GX-B1380/20-3-23006	2023. 4. 22	所检项目 合格			

229	GX-B1380/20-3-23007	2023. 4. 22	所检项目 合格	
230	GX-B1382/21-3-23009	2023. 4. 28	合格	

231	GX-B1382/21-3-23010	2023. 4. 28	合格	
232	GX-B1382/21-3-23011	2023. 4. 28	合格	

233	GX-B1382/21-3-23012	2023. 4. 28	合格		 A worker wearing a grey jacket, blue pants, a red hard hat, and safety glasses stands on a construction site. A large, dark pipe is visible in the foreground. The background shows structural steel beams and other construction elements. A yellow timestamp '2023.4.14' is visible in the bottom right corner of the photo.	
234	GX-B1382/21-3-23013	2023. 4. 28	合格		 A worker wearing a grey jacket, blue pants, a red hard hat, and safety glasses stands on a construction site. The worker is positioned behind a red metal railing. In the background, another worker is visible on a higher level of the structure. A yellow timestamp '2023.4.14' is visible in the bottom right corner of the photo.	

235	GX-B1382/21-3-23014	2023. 4. 28	合格			
-----	---------------------	-------------	----	--	---	--