










序号	报告编号	发布日期	结论	影像资料
14	GX-B1415/22-2-23005	2023. 5. 5	综合判定：合格	 <p>2023/04/04</p>
15	GX-B1559/22-2-23007	2023. 5. 5	所检项目合格	 <p>2023/04/17</p>

16	GX-B1499/21-2-23046	2023.5.6	所检项目合格。	
17	GX-B1499/21-2-23047	2023.5.6	所检项目合格。	
18	GX-B1499/21-2-23048	2023.5.6	除吨水百米电耗超限外,其余所检项目合格。 。	




19	GX-B1499/21-2-23049	2023.5.6	除吨水百米电耗超限外,其余所检项目合格。 。	
20	GX-B1328/20-2-23070	2023.5.9	本次共检绝缘手套2只,2只所检项目合格。 。	
21	GX-B1328/20-2-23071	2023.5.9	本次共检绝缘鞋2只,2只所检项目合格。	

22	GX-B1328/20-2-23072	2023. 5. 9	本次所检项目合格。	 A photograph showing an indoor inspection site. In the foreground, there is a yellow and green safety barrier. To the right, a red safety net is stretched across the area. In the background, there are several pieces of electrical equipment, including what appears to be a transformer or generator, and a person wearing a red hard hat and safety vest is standing near the equipment. The floor is light-colored and the walls are white. A timestamp '2023/05/09' is visible in the bottom right corner of the photo.
23	GX-B1328/20-2-23073	2023. 5. 9	本次所检项目合格。	 A photograph showing an indoor inspection site, similar to the one in row 22. It features a yellow and green safety barrier, a red safety net, and electrical equipment in the background. A person in a red hard hat and safety vest is visible. The timestamp '2023/05/09' is present in the bottom right corner.
24	GX-B1539/22-2-23002	2023. 5. 11	所检项目合格。	 A photograph of an outdoor inspection site. A large yellow loader is the central focus. Two people wearing safety gear are standing near the loader. In the foreground, there is a black equipment case with an orange bag on top. The ground is paved. The background shows a clear sky and some distant structures. A timestamp '2023/05/11' is visible in the bottom right corner.




25	GX-B1539/22-2-23003	2023. 5. 11	所检项目合格。	
26	GX-B1424/20-2-23006	2023. 5. 10	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	
27	GX-B1424/20-2-23007	2023. 5. 10	依据NB/T 10176-2019 单轨吊车所检项目合格。 。	

28	GX-B1310/21-2-23078	2023. 5. 10	符合标准要求			
29	GX-B1310/21-2-23079	2023. 5. 10	符合标准要求			
30	GX-B1310/21-2-23051	2023. 5. 9	符合标准要求。			

31	GX-B1310/21-2-23052	2023. 5. 9	符合标准要求。	
32	GX-B1310/21-2-23053	2023. 5. 9	符合标准要求。	
33	GX-B1310/21-2-23054	2023. 5. 9	符合标准要求。	

34	GX-B1310/21-2-23055	2023. 5. 9	符合标准要求。	 <p>2023/04/09</p>
35	GX-B1310/21-2-23056	2023. 5. 9	符合标准要求。	 <p>2023/04/10</p>
36	GX-B1310/21-2-23057	2023. 5. 9	未发现超过Φ2mm当量直径的缺陷。	 <p>2023/04/09</p>

37	GX-B1428/21-2-23057	2023. 5. 9	无缺陷痕迹显示。	
38	GX-B1310/21-2-23058	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
39	GX-B1428/21-2-23058	2023. 5. 9	无缺陷痕迹显示。	

40	GX-B1310/21-2-23059	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
41	GX-B1428/21-2-23059	2023. 5. 9	无缺陷迹痕显示。	
42	GX-B1310/21-2-23060	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

43	GX-B1428/21-2-23060	2023. 5. 9	无缺陷痕迹显示。		
44	GX-B1310/21-2-23061	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		
45	GX-B1310/21-2-23062	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。		




46	GX-B1310/21-2-23063	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
47	GX-B1310/21-2-23064	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	
48	GX-B1310/21-2-23065	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	


49	GX-B1310/21-2-23066	2023. 5. 9	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A worker wearing a headlamp and a dark jacket is inspecting a surface in a dark environment. The worker is holding a handheld device that displays some information. The date 2023/04/09 is visible in the bottom right corner of the image.
50	GX-B1310/21-2-23067	2023. 5. 9	符合标准要求。	 A worker wearing a red hard hat and a light-colored jacket is inspecting a large red cylindrical object. The worker is holding a handheld device. The date 2023/04/10 is visible in the bottom right corner of the image.
51	GX-B1423/20-2-23022	2023. 5. 10	综合判定：合格。	 A yellow truck is parked in an outdoor area. A worker wearing a red hard hat and a light-colored jacket is standing next to the truck. The date 2023/05/22 is visible in the bottom right corner of the image.




52	GX-B1423/20-2-23023	2023. 5. 10	综合判定：合格。	 2023/03/22
53	GX-B1423/20-2-23024	2023. 5. 10	综合判定：合格。	 2023/03/22
54	GX-B1423/20-2-23025	2023. 5. 10	综合判定：合格。	 2023/03/22

55	GX-B1423/20-2-23026	2023. 5. 10	综合判定：合格。	 A photograph showing a yellow truck with a worker in a red hard hat and blue mask standing next to it. A black toolbox and an orange container are on the ground in front of the truck. The license plate is visible as A-BCC01711. A timestamp '2023/03/22' is in the bottom right corner.
56	GX-B1423/20-2-23027	2023. 5. 10	综合判定：合格。	 A photograph showing two workers in red hard hats and blue masks standing in front of a yellow truck. One worker is holding a black toolbox. The license plate is A-BCC01711. A timestamp '2023/03/22' is in the bottom right corner.
57	GX-B1423/20-2-23028	2023. 5. 10	综合判定：合格。	 A photograph showing a worker in a red hard hat and blue mask operating a yellow truck from the driver's seat. The worker is wearing a blue face mask. A timestamp '2023/03/22' is in the bottom right corner.

58	GX-B1423/20-2-23029	2023. 5. 10	综合判定：合格。	
59	GX-B1300/20-2-23006	2023. 5. 10	综合判定：合格。	
60	GX-B1534/20-2-23008	2023. 5. 10	所检项目合格。	




61	GX-B1500/21-2-23051	2023. 5. 10	综合判定:合格。		
62	GX-B1500/21-2-23052	2023. 5. 10	综合判定:合格。		
63	GX-B1500/21-2-23053	2023. 5. 10	综合判定:合格。		




64	GX-B1500/21-2-23040	2023. 5. 10	综合判定:合格。	
65	GX-B1500/21-2-23041	2023. 5. 10	综合判定:合格。	
66	GX-B1500/21-2-23042	2023. 5. 10	综合判定:合格。	




67	GX-B1500/21-2-23043	2023. 5. 10	综合判定:合格。	
68	GX-B1500/21-2-23044	2023. 5. 10	综合判定:合格。	
69	GX-B1500/21-2-23045	2023. 5. 10	综合判定:合格。	

70	GX-B1500/21-2-23046	2023. 5. 10	综合判定:合格。	
71	GX-B1500/21-2-23047	2023. 5. 10	综合判定:合格。	
72	GX-B1500/21-2-23048	2023. 5. 10	综合判定:合格。	

73	GX-B1500/21-2-23049	2023. 5. 10	综合判定:合格。	
74	GX-B1500/21-2-23050	2023. 5. 10	综合判定:合格。	
75	GX-B1350/21-2-23020	2023. 5. 11	所检项目合格。	

76	GX-B1451/20-2-23133~23134	2023. 5. 10	本次共检高压开关柜2台，2台所检项目合格。		
77	GX-B1309/21-2-23005	2023. 5. 10	所检项目合格。		
78	GX-B1500/21-2-23020	2023. 5. 10	综合判定：合格。		




79	GX-B1500/21-2-23021	2023. 5. 10	综合判定：合格。	
80	GX-B1500/21-2-23022	2023. 5. 10	综合判定：合格。	
81	GX-B1309/21-2-23007	2023. 5. 10	所检项目合格。	

82	GX-B1500/21-2-23029	2023. 5. 10	综合判定：合格。	
83	GX-B1500/21-2-23030	2023. 5. 10	综合判定：合格。	
84	GX-B1500/21-2-23031	2023. 5. 10	综合判定：合格。	



85	GX-B1500/21-2-23032	2023. 5. 10	综合判定：合格。	
86	GX-B1500/21-2-23033	2023. 5. 10	综合判定：合格。	
87	GX-B1500/21-2-23034	2023. 5. 10	综合判定：合格。	



88	GX-B1500/21-2-23035	2023. 5. 10	综合判定：合格。		
89	GX-B1500/21-2-23036	2023. 5. 10	所检项目合格。		
90	GX-B1500/21-2-23037	2023. 5. 10	所检项目合格。		

91	GX-B1500/21-2-23038	2023. 5. 10	所检项目合格。	
92	GX-B1416/22-2-23014	2023. 5. 10	综合判定：合格。	
93	GX-B1312/20-2-23115~23116	2023. 5. 9	本次共检电力变压器2台，2台电力变压器所检项目合格。	

94	GX-B1313/21-2-23066~23067	2023. 5. 11	所检项目合格		
95	GX-B1322/21-2-23067~23068	2023. 5. 11	所检项目合格		
96	GX-B1321/20-2-23101	2023. 5. 11	所检项目合格		

97	GX-B1321/20-2-23102~23103	2023. 5. 11	本次共检电力电缆 2条，2条电力电缆所检 项目合格。	
98	GX-B1307/20-2-23050	2023. 5. 9	综合判定：合格。	
99	GX-B1307/20-2-23051	2023. 5. 9	综合判定：合格。	

100	GX-B1307/20-2-23052	2023. 5. 9	综合判定：合格。	
101	GX-B1307/20-2-23053	2023. 5. 10	综合判定：合格。	
102	GX-B1307/20-2-23054	2023. 5. 10	综合判定：合格。	

103	GX-B1310/21-2-23069	2023. 5. 10	符合标准要求		
104	GX-B1427/21-2-23069	2023. 5. 10	符合标准要求		
105	GX-B1310/21-2-23070	2023. 5. 10	符合标准要求		

106	GX-B1427/21-2-23070	2023. 5. 10	符合标准要求	
107	GX-B1310/21-2-23071	2023. 5. 10	符合标准要求	
108	GX-B1427/21-2-23071	2023. 5. 10	符合标准要求	

109	GX-B1310/21-2-23072	2023. 5. 10	符合标准要求	
110	GX-B1427/21-2-23072	2023. 5. 10	符合标准要求	
111	GX-B1310/21-2-23073	2023. 5. 11	符合标准要求	

112	GX-B1427/21-2-23073	2023. 5. 11	符合标准要求		
113	GX-B1310/21-2-23074	2023. 5. 11	符合标准要求		
114	GX-B1427/21-2-23074	2023. 5. 11	符合标准要求		