









序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-4-23131	2023. 9. 1	符合标准要求	
2	GX-B1310/21-4-23132	2023. 9. 1	符合标准要求	
3	GX-B1310/21-4-23133	2023. 9. 1	符合标准要求	

4	GX-B1310/21-4-23134	2023. 9. 1	符合标准要求	
5	GX-B1310/21-4-23135	2023. 9. 1	符合标准要求	
6	GX-B1310/21-4-23136	2023. 9. 1	符合标准要求	
7	GX-B1310/21-4-23137	2023. 9. 1	符合标准要求	

8	GX-B1310/21-4-23138	2023. 9. 1	符合标准要求	 <p>2023. 8. 10</p>
9	GX-B1310/21-4-23139	2023. 9. 1	符合标准要求	 <p>2023. 8. 9</p>
10	GX-B1310/21-4-23140	2023. 9. 1	符合标准要求	 <p>2023. 8. 9</p>
11	GX-B1310/21-4-23141	2023. 9. 1	符合标准要求	 <p>2023. 8. 10</p>

12	GX-B1428/21-4-23140	2023. 9. 1	无缺陷迹痕显示。	
13	GX-B1428/21-4-23141	2023. 9. 1	无缺陷迹痕显示。	
14	GX-B1328/20-4-23169	2023. 9. 4	本次共检绝缘手套10只， 10只所检项目合格。	
15	GX-B1328/20-4-23170	2023. 9. 4	本次共检绝缘鞋10只，10 只所检项目合格。	

16	GX-B1328/20-4-23171	2023. 9. 4	本次共检验电器5支，5支所检项目合格。	
17	GX-B1328/20-4-23172	2023. 9. 4	本次共检短路接地线5套，5套所检项目合格。	
18	GX-B1500/21-4-23004	2023. 9. 5	综合判定：合格。	
19	GX-B1500/21-4-23005	2023. 9. 5	综合判定：合格。	

20	GX-B1500/21-4-23006	2023. 9. 5	综合判定：合格。	
21	GX-B1309/21-4-23002	2023. 9. 5	所检项目合格。	
22	GX-B1416/22-4-23023	2023. 9. 5	综合判定：合格	
23	GX-B1416/22-4-23024	2023. 9. 5	综合判定：合格	

24	GX-B1321/20-4-23921~23922	2023. 9. 6	本次共检电力电缆2条，2条电力电缆所检项目合格。	 <p>2023/8/23</p>
25	GX-B1350/21-4-23066	2023. 9. 6	本次共检验接地装置4处，4处所检项目合格。	 <p>2023/8/23</p>
26	GX-B1312/20-4-23565~23566	2023. 9. 6	本次共检电力变压器2台，2台所检项目合格。	 <p>2023/8/23</p>