

序号	报告编号	发布日期	结论	影像资料
7	GX-B1312/20-P-23121	2023. 10. 10	所检项目合格。	
8	GX-B1339/21-P-23023	2023. 10. 10	所检项目合格	
9	GX-B1339/21-P-23024	2023. 10. 10	所检项目合格	

10	GX-B1339/21-P-23025	2023. 10. 10	所检项目合格		
11	GX-B1339/21-P-23026	2023. 10. 10	所检项目合格		
12	GX-B1350/21-P-23020	2023. 10. 10	所检项目合格。		

13	GX-B1495/20-P-231094	2023. 10. 11	所检项目合格。	
14	GX-B1495/20-P-231095-231096	2023. 10. 11	本次共检电流互感器2只，2只电流互感器所检项目合格。	
15	GX-B1329/21-P-23312	2023. 10. 11	本次共检氧化锌避雷器1组，1组氧化锌避雷器所检项目合格。	

16	GX-B1321/20-P-23158~23159	2023. 10. 11	本次共检电力电缆2条，2条电力电缆所检项目合格。	 <p>2023.9.25</p>
17	GX-B1339/21-P-23027	2023. 10. 12	所检项目合格	 <p>2023.9.28</p>
18	GX-B1339/21-P-23028	2023. 10. 12	所检项目合格	 <p>2023.9.29</p>

19	GX-B1339/21-P-23029	2023. 10. 12	所检项目合格	
20	GX-B1339/21-P-23030	2023. 10. 12	所检项目合格	
21	GX-B1339/21-P-23031	2023. 10. 12	所检项目合格	

22	GX-B1339/21-P-23032	2023. 10. 12	所检项目合格	
23	GX-B1417/22-P-231473	2023. 10. 13	综合判定：合格。	
24	GX-B1417/22-P-231472	2023. 10. 13	综合判定：合格。	

25	GX-B1306/21-P-23051	2023. 10. 12	所检项目合格	 A photograph showing a worker wearing a red hard hat and a grey work jacket. The worker is standing next to a large blue industrial structure, possibly a piece of machinery or a container, and appears to be inspecting or working on it. The background is dark, suggesting an indoor or nighttime setting. A small timestamp '2023.9.26' is visible in the bottom right corner of the photo.
----	---------------------	--------------	--------	--