

序号	报告编号	发布日期	结论	影像资料
1	GX-B1499/23-Y-24001	2024年2月1日	所检项目合格。	
2	GX-B1499/23-Y-24002	2024年2月1日	所检项目合格。	
3	GX-B1499/23-Y-24003	2024年2月1日	所检项目合格。	

4	GX-B1310/21-Y-24007	2024年1月31日	符合标准要求。	
5	GX-B1310/21-Y-24008	2024年1月31日	符合标准要求。	
6	GX-B1310/21-Y-24009	2024年1月31日	符合标准要求。	

7	GX-B1310/21-Y-24010	2024年1月31日	符合标准要求。	
8	GX-B1310/21-Y-24011	2024年1月31日	符合标准要求。	
9	GX-B1310/21-Y-24012	2024年1月31日	符合标准要求。	

10	GX-B1310/21-Y-24013	2024年1月31日	符合标准要求。	 2024/1/6	
11	GX-B1310/21-Y-24014	2024年1月31日	符合标准要求。	 2024/1/7	
12	GX-B1310/21-Y-24015	2024年1月31日	符合标准要求。	 2024/1/7	

13	GX-B1310/21-Y-24016	2024年1月31日	符合标准要求。		
14	GX-B1310/21-Y-24017	2024年1月31日	符合标准要求。		
15	GX-B1310/21-Y-24018	2024年1月31日	符合标准要求。		

16	GX-B1310/21-Y-24019	2024年1月31日	符合标准要求。	
17	GX-B1385/21-Y-24002	2024年2月1日	所检项目合格。	
18	GX-B1385/21-Y-24003	2024年2月1日	所检项目合格。	

19	GX-B1385/21-Y-24004	2024年2月1日	所检项目合格。	
20	GX-B1385/21-Y-24005	2024年2月1日	所检项目合格。	
21	GX-B1385/21-Y-24006	2024年2月1日	所检项目合格。	

22	GX-B1385/21-Y-24007	2024年2月1日	所检项目合格。		
23	GX-B1385/21-Y-24008	2024年2月1日	所检项目合格。		
24	GX-B1385/21-Y-24009	2024年2月1日	所检项目合格。		

25	GX-B1385/21-Y-24010	2024年2月1日	所检项目合格。	 2024.1.7	
26	GX-B1385/21-Y-24011	2024年2月1日	所检项目合格。	 2024.1.7	
27	GX-B1385/21-Y-24012	2024年2月1日	所检项目合格。	 2024.1.8	

28	GX-B1385/21-Y-24013	2024年2月1日	所检项目合格。		
29	GX-B1385/21-Y-24014	2024年2月1日	所检项目合格。		
30	GX-B1563/21-Y-24001	2024年2月1日	所检项目合格。		

31	GX-B1563/21-Y-24002	2024年2月1日	所检项目合格。	 A yellow water truck with 'CM-02' on the side, parked on a snowy surface. Two people are standing next to it. The truck has '矿用洒水车' (Mining Water Sprayer) written on the tank.
32	GX-B1563/21-Y-24003	2024年2月1日	所检项目合格。	 A yellow water truck with 'CM-03' on the side, parked on a snowy surface. Two people are standing next to it. The truck has '矿用洒水车' (Mining Water Sprayer) written on the tank.
33	GX-B1563/21-Y-24004	2024年2月1日	所检项目合格。	 A yellow water truck with 'CM-05' on the side, parked on a snowy surface. Two people are standing next to it. The truck has '矿用洒水车' (Mining Water Sprayer) written on the tank.

34	GX-B1563/21-Y-24005	2024年2月1日	所检项目合格。	
35	GX-B1539/22-Y-24008	2024年2月1日	所检项目合格。	

36	GX-B1539/22-Y-24009	2024年2月1日	所检项目合格。	
37	GX-B1539/22-Y-24010	2024年2月1日	所检项目合格。	

38	GX-B1539/22-Y-24011	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---

39	GX-B1539/22-Y-24012	2024年2月1日	所检项目合格。	
40	GX-B1557/22-Y-24001	2024年2月1日	所检项目合格。	

41	GX-B1557/22-Y-24002	2024年2月1日	所检项目合格。	
42	GX-B1556/22-Y-24001	2024年2月1日	所检项目合格。	

43	GX-B1539/22-Y-24013	2024年2月1日	所检项目合格。	
44	GX-B1539/22-Y-24014	2024年2月1日	所检项目合格。	

45	GX-B1539/22-Y-24015	2024年2月1日	所检项目合格。	 <p>A photograph showing a yellow CAT wheel loader parked outdoors in a snowy environment. Two people, a man in a dark jacket and a woman in a long brown coat, are standing in front of the machine. The date '2024/1/4' is visible in the bottom right corner of the photo.</p>
46	GX-B1539/22-Y-24016	2024年2月1日	所检项目合格。	 <p>A photograph showing a yellow LUGONG wheel loader parked indoors in a large warehouse or garage. Two people, a woman in a long green coat and a man in a blue work uniform, are standing in front of the machine. The date '2024/1/4' is visible in the bottom right corner of the photo.</p>

47	GX-B1499/23-Y-24004	2024年2月2日	所检项目合格。	 <p>A photograph showing a worker in a green winter coat and hat inspecting a large blue industrial motor. The motor is connected to a network of red pipes. The worker is holding a device, possibly a handheld diagnostic tool. A yellow timestamp '2024/1/9' is visible in the bottom right corner of the photo.</p>
48	GX-B1499/23-Y-24005	2024年2月2日	所检项目合格。	 <p>A photograph showing a worker in a green winter coat and hat inspecting a large green industrial motor. The motor is connected to a network of red pipes. The worker is holding a device, possibly a handheld diagnostic tool. A yellow timestamp '2024/1/9' is visible in the bottom right corner of the photo.</p>

49	GX-B1499/23-Y-24006	2024年2月2日	所检项目合格。	 A worker wearing a green protective suit and a silver helmet is operating a green lathe machine in a factory. The worker is looking at a device in their hands. A yellow timestamp '2024/1/10' is visible in the bottom right corner of the photo.
50	GX-B1385/21-Y-24017	2024年2月1日	所检项目合格。	 A worker wearing a grey uniform and a black hat is standing on a metal walkway in an industrial facility. The worker is looking at a device in their hands. The background shows industrial structures and a bright light source.

51	GX-B1385/21-Y-24018	2024年2月1日	所检项目合格。	 
----	---------------------	-----------	---------	--

52	GX-B1385/21-Y-24019	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---


53	GX-B1385/21-Y-24020	2024年2月1日	所检项目合格。	 <p>A photograph showing a worker in a grey uniform and black hat using a handheld device on a metal structure. The worker is standing on a platform with a red safety fence. The date 2024/1/11 is visible in the bottom right corner of the photo.</p>
----	---------------------	-----------	---------	---

54	GX-B1385/21-Y-24021	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---

55	GX-B1385/21-Y-24022	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---

56	GX-B1385/21-Y-24023	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---

57	GX-B1385/21-Y-24024	2024年2月1日	所检项目合格。	
----	---------------------	-----------	---------	---

58	GX-B1385/21-Y-24025	2024年2月1日	所检项目合格。	 A photograph showing a worker in a green winter coat and hat using a handheld device on a construction site. The worker is standing next to a blue corrugated metal structure. The background shows a snowy landscape and a red structure. A yellow timestamp '2024/1/12' is visible in the bottom right corner of the photo.
----	---------------------	-----------	---------	---

59	GX-B1539/22-Y-24017	2024年2月1日	所检项目合格。	
60	GX-B1539/22-Y-24018	2024年2月1日	所检项目合格。	

61	GX-B1539/22-Y-24019	2024年2月1日	所检项目合格。	
62	GX-B1539/22-Y-24020	2024年2月1日	所检项目合格。	

63	GX-B1539/22-Y-24021	2024年2月1日	所检项目合格。	
64	GX-B1561/20-Y-24005	2024年2月2日	所检项目合格。	

65	GX-B1561/20-Y-24006	2024年2月2日	所检项目合格。	
66	GX-B1561/20-Y-24001	2024年2月2日	所检项目合格。	


67	GX-B1561/20-Y-24002	2024年2月2日	所检项目合格。	 <p>A photograph showing a person wearing a brown winter coat and a black hat, standing in a control room. They are positioned in front of a desk with a computer monitor and various control panels. The room has blue walls and a window. A yellow timestamp '2024/1/4' is visible in the bottom right corner of the image.</p>
68	GX-B1561/20-Y-24003	2024年2月2日	所检项目合格。	 <p>A photograph showing two people in a control room. One person is wearing a red hard hat and a dark jacket, standing. The other person is wearing a brown winter coat and a black hat, sitting at a desk with a computer monitor. The room has blue walls and a window. A yellow timestamp '2024/1/4' is visible in the bottom right corner of the image.</p>

69	GX-B1561/20-Y-24004	2024年2月2日	所检项目合格。	 <p>A photograph showing a person wearing a green winter jacket and a black hat, sitting in the driver's seat of a vehicle. They are looking at a control panel with various gauges and buttons. The interior of the cab is visible, including a window and some equipment. A yellow timestamp '2024/1/4' is in the bottom right corner.</p>
70	GX-B1559/22-Y-24001	2024年2月2日	所检项目合格。	 <p>A photograph of a large wheel loader in an industrial setting. A person wearing a blue jacket and a hard hat is operating the machine. The number '4' is painted on the side of the loader. The background shows a metal structure, possibly part of a mine or factory. A yellow timestamp '2024/1/28' is in the bottom right corner.</p>


71	GX-B1559/22-Y-24002	2024年2月2日	所检项目合格。	
72	GX-B1495/20-Y-24001-24014	2024年2月2日	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	

73	GX-B1321/20-Y-24019~24022	2024年2月2日	综合判定：合格	 <p>2024/1/27</p>
74	GX-B1310/21-Y-24020	2024年2月2日	符合标准要求。	 <p>2024/1/10</p>

75	GX-B1310/21-Y-24021	2024年2月2日	符合标准要求。	
76	GX-B1310/21-Y-24022	2024年2月2日	符合标准要求。	

77	GX-B1310/21-Y-24023	2024年2月2日	符合标准要求。		
78	GX-B1310/21-Y-24024	2024年2月2日	符合标准要求。		
79	GX-B1310/21-Y-24025	2024年2月2日	符合标准要求。		

80	GX-B1310/21-Y-24026	2024年2月2日	符合标准要求。	 2024/1/12	
81	GX-B1310/21-Y-24027	2024年2月2日	符合标准要求。	 2024/1/12	
82	GX-B1310/21-Y-24028	2024年2月2日	符合标准要求。	 2024/1/12	

83	GX-B1416/22-Y-24015	2024年2月6日	综合判定：合格	 <p>2024/1/27</p>
84	GX-B1416/22-Y-24016	2024年2月6日	综合判定：合格	 <p>2024/1/27</p>


85

GX-B1354/20-Y-24004

2024年2月6日

合格。



86	GX-B1404/20-Y-24001	2024年2月6日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
----	---------------------	-----------	---	---

87	GX-B1404/20-Y-24002	2024年2月6日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>2024/1/13</p>
----	---------------------	-----------	---	--

88	GX-B1547/20-Y-24001~24014	2024年2月6日	本次共检继电保护装置14台，14台继电保护装置所检项目合格。	
----	---------------------------	-----------	--------------------------------	---

89	GX-B1547/20-Y-24015~24030	2024年2月6日	本次共检继电保护装置16台，16台继电保护装置所检项目合格。	
----	---------------------------	-----------	--------------------------------	---

90	GX-B1547/20-Y-24031~24046	2024年2月6日	本次共检继电保护装置16台，16台继电保护装置所检项目合格。	
----	---------------------------	-----------	--------------------------------	---

91	GX-B1547/20-Y-24047~24056	2024年2月6日	本次共检继电保护装置10台，10台继电保护装置所检项目合格。	
----	---------------------------	-----------	--------------------------------	---

92	GX-B1547/20-Y-24057~24071	2024年2月6日	本次共检继电保护装置15台，15台继电保护装置所检项目合格。	
93	GX-B1539/22-Y-24022	2024年2月4日	所检项目合格。	

94	GX-B1539/22-Y-24023	2024年2月4日	所检项目合格。	
95	GX-B1539/22-Y-24024	2024年2月4日	所检项目合格。	

96	GX-B1539/22-Y-24025	2024年2月4日	所检项目合格。	
97	GX-B1539/22-Y-24026	2024年2月4日	所检项目合格。	

98	GX-B1521/20-Y-24054	2024年2月5日	所检项目合格。	
99	GX-B1521/20-Y-24055	2024年2月5日	所检项目合格。	

100	GX-B1521/20-Y-24056	2024年2月5日	所检项目合格。	 A photograph showing a person wearing a dark fur-lined hat and a tan camouflage jacket, sitting in the driver's seat of a vehicle. The person is looking down at a control panel or instrument cluster. The image has a yellow timestamp '2024/1/28' in the bottom right corner.
-----	---------------------	-----------	---------	--

101	GX-B1521/20-Y-24057	2024年2月5日	所检项目合格。	
102	GX-B1521/20-Y-24058	2024年2月5日	所检项目合格。	

103	GX-B1521/20-Y-24059	2024年2月5日	所检项目合格。	
104	GX-B1521/20-Y-24060	2024年2月5日	所检项目合格。	

105	GX-B1521/20-Y-24061	2024年2月5日	所检项目合格。	
106	GX-B1521/20-Y-24062	2024年2月5日	所检项目合格。	

107	GX-B1521/20-Y-24063	2024年2月5日	所检项目合格。	 A photograph showing a person wearing a winter jacket and a black beanie sitting in the operator's seat of a piece of heavy machinery. The person is looking down at a control panel. The date stamp '2024/1/28' is visible in the bottom right corner of the image.
108	GX-B1521/20-Y-24064	2024年2月5日	所检项目合格。	 A photograph of an orange Hitachi excavator. The name 'HITACHI' and the number '02' are visible on the boom. A person is standing next to the excavator. The date stamp '2024/1/28' is visible in the bottom right corner of the image.

109	GX-B1521/20-Y-24065	2024年2月5日	所检项目合格。	
110	GX-B1521/20-Y-24066	2024年2月5日	所检项目合格。	

111	GX-B1557/22-Y-24004	2024年2月4日	所检项目合格。	
112	GX-B1328/20-Y-24014	2024年2月5日	所检项目合格。	

113	GX-B1328/20-Y-24015	2024年2月6日	本次共检便携式接地和接地短路装置3组，3组便携式接地和接地短路装置合格。	
114	GX-B1306/23-Y-24013	2024年2月5日	综合判定：合格。	
115	GX-B1306/23-Y-24014	2024年2月5日	综合判定：合格。	

116	GX-B1306/23-Y-24015	2024年2月5日	综合判定：合格。	 A worker in a white protective suit and cap is operating a red industrial machine labeled "BAE-7A". The worker is looking at a document. A yellow timestamp "2024/1/9" is visible in the bottom right corner of the photo.
117	GX-B1306/23-Y-24016	2024年2月5日	综合判定：合格。	 A worker in a green protective suit and cap is using a tool on a wall next to a large industrial unit. A yellow timestamp "2024/1/9" is visible in the bottom right corner of the photo.
118	GX-B1306/23-Y-24017	2024年2月5日	综合判定：合格。	 A worker in a white protective suit and helmet is operating a red industrial machine labeled "BAE-11A". A yellow timestamp "2024/1/9" is visible in the bottom right corner of the photo.

119	GX-B1306/23-Y-24018	2024年2月5日	综合判定：合格。		
120	GX-B1306/23-Y-24019	2024年2月5日	综合判定：合格。		

121	GX-B1539/22-Y-24008	2024年2月1日	所检项目合格。	
122	GX-B1539/22-Y-24009	2024年2月1日	所检项目合格。	

123	GX-B1539/22-Y-24010	2024年2月1日	所检项目合格。	
124	GX-B1539/22-Y-24011	2024年2月1日	所检项目合格。	

125	GX-B1539/22-Y-24012	2024年2月1日	所检项目合格。	
-----	---------------------	-----------	---------	---