




序号	报告编号	发布日期	结论	影像资料
28	GX-B1495/20-5-241181~241189	2024/6/6	本次共检防爆型高压配电装置9台，9台防爆型高压配电装置所检项目合格。	
29	GX-B1559/22-5-24004	2024/6/7	所检项目合格。	
30	GX-B1328/20-5-24101	2024. 6. 7	本次共检验电器2支，2支验电器合格。	

31	GX-B1328/20-5-24102	2024.6.7	本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。	
32	GX-B1321/20-5-24854~24855	2024.6.7	本次共检电力电缆2条，2条电力电缆所检项目合格。	
33	GX-B1495/20-5-241177-241180	2024.6.7	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	




34	GX-B1308/23-5-24013	2024/6/7	综合判定：合格。	 <p>DSJ_0000000_000000 2024/05/11 11:17:38</p>
35	GX-B1308/23-5-24014	2024/6/7	综合判定：合格。	 <p>2024/05/11</p>
36	GX-B1300/23-5-24017	2024/6/11	综合判定：合格。	 <p>2024/05/15</p>




37	GX-B1300/23-5-24018	2024/6/11	综合判定：合格。	 <p>2024/06/16</p>
38	GX-B1424/20-5-24050	2024/6/12	依据NB/T 10176-2019单轨吊 车所检项目合格。	 <p>2024/5/25</p>
39	GX-B1424/20-5-24051	2024/6/12	依据NB/T 10176-2019单轨吊 车所检项目合格。	 <p>2024/5/25</p>

40	GX-B1424/20-5-24052	2024/6/12	依据NB/T 10176-2019单轨吊车所检项目合格。	
41	GX-B1424/20-5-24053	2024/6/12	依据NB/T 10176-2019单轨吊车综合判定合格。	
42	GX-B1404/20-5-24011	2024. 6. 12	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。	



43	GX-B1404/20-5-24012	2024. 6. 12	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	
44	GX-B1500/21-5-24043	2024. 6. 12	<p>综合判定：合格。</p>	
45	GX-B1500/21-5-24044	2024. 6. 12	<p>综合判定：合格。</p>	




46	GX-B1500/21-5-24045	2024. 6. 12	综合判定：合格。	 A worker wearing a white hard hat and a reflective safety jacket is using a handheld electronic device in a dark tunnel. The date stamp '2024/5/21' is visible in the bottom right corner of the image.
47	GX-B1500/21-5-24046	2024. 6. 12	综合判定：合格。	 A worker wearing a white hard hat and a reflective safety jacket is looking at a handheld electronic device in a dark tunnel. The date stamp '2024/5/21' is visible in the bottom right corner of the image.
48	GX-B1500/21-5-24047	2024. 6. 12	综合判定：合格。	 A worker wearing a red hard hat and a blue jacket is using a handheld electronic device in a tunnel. The date stamp '2024/5/21' is visible in the bottom right corner of the image.




49	GX-B1500/21-5-24048	2024. 6. 12	综合判定：合格。	
50	GX-B1500/21-5-24049	2024. 6. 12	综合判定：合格。	
51	GX-B1500/21-5-24050	2024. 6. 12	综合判定：合格。	


52	GX-B1500/21-5-24051	2024. 6. 12	综合判定：合格。	 <p>2024/5/21</p>
53	GX-B1500/21-5-24052	2024. 6. 12	综合判定：合格。	 <p>2024/5/21</p>
54	GX-B1500/21-5-24053	2024. 6. 12	综合判定：合格。	 <p>2024/5/21</p>

55	GX-B1500/21-5-24054	2024. 6. 12	综合判定：合格。	
56	GX-B1500/21-5-24055	2024. 6. 12	综合判定：合格。	
57	GX-B1500/21-5-24056	2024. 6. 12	综合判定：合格。	

58	GX-B1500/21-5-24057	2024. 6. 12	综合判定：合格。	
59	GX-B1500/21-5-24058	2024. 6. 12	综合判定：合格。	
60	GX-B1500/21-5-24059	2024. 6. 12	综合判定：合格。	

61	GX-B1500/21-5-24060	2024. 6. 12	综合判定：合格。	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective stripes. The worker is holding a handheld device, possibly a detector or scanner, and is positioned in a tunnel or underground setting. A date stamp '2024/5/21' is visible in the bottom right corner of the image.
62	GX-B1500/21-5-24061	2024. 6. 12	综合判定：合格。	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective stripes. The worker is using a handheld device, possibly a scanner or detector, in a tunnel environment. A date stamp '2024/5/21' is visible in the bottom right corner of the image.
63	GX-B1500/21-5-24062	2024. 6. 12	综合判定：合格。	 A black and white photograph of a worker wearing a hard hat and a safety vest with reflective stripes. The worker is inspecting a large, dark pipe or tunnel structure. A date stamp '2024/5/21' is visible in the bottom right corner of the image.

64	GX-B1500/21-5-24063	2024. 6. 12	综合判定：合格。			
65	GX-B1500/21-5-24064	2024. 6. 12	综合判定：合格。			
66	GX-B1500/21-5-24065	2024. 6. 12	综合判定：合格。			




67	GX-B1500/21-5-24066	2024. 6. 12	综合判定：合格。	
68	GX-B1500/21-5-24067	2024. 6. 12	综合判定：合格。	
69	GX-B1500/21-5-24068	2024. 6. 12	综合判定：合格。	

70	GX-B1500/21-5-24069	2024. 6. 12	综合判定：合格。	
71	GX-B1500/21-5-24070	2024. 6. 12	综合判定：合格。	
72	GX-B1500/21-5-24071	2024. 6. 12	综合判定：合格。	

73	GX-B1500/21-5-24072	2024. 6. 12	综合判定：合格。	
74	GX-B1500/21-5-24073	2024. 6. 12	综合判定：合格。	
75	GX-B1500/21-5-24074	2024. 6. 12	综合判定：合格。	

76	GX-B1500/21-5-24075	2024. 6. 12	综合判定：合格。	
77	GX-B1500/21-5-24076	2024. 6. 12	综合判定：合格。	
78	GX-B1500/21-5-24077	2024. 6. 12	综合判定：合格。	

79	GX-B1309/21-5-24012	2024. 6. 12	综合判定：合格。	
80	GX-B1309/21-5-24013	2024. 6. 12	综合判定：合格。	
81	GX-B1309/21-5-24014	2024. 6. 12	综合判定：合格。	

82	GX-B1309/21-5-24015	2024. 6. 12	综合判定：合格。	 A worker wearing a blue uniform and a red hard hat is kneeling in a tunnel, operating a handheld electronic device. The tunnel walls are rocky and there is some equipment in the background. A yellow timestamp '2024/5/21' is visible in the bottom right corner of the image.
83	GX-B1309/21-5-24016	2024. 6. 12	综合判定：合格。	 A worker wearing a blue uniform and a red hard hat is standing in a tunnel, looking towards the camera. The tunnel is dimly lit with some equipment visible in the background. A yellow timestamp '2024/5/21' is visible in the bottom right corner of the image.
84	GX-B1309/21-5-24017	2024. 6. 12	综合判定：合格。	 A worker wearing a blue uniform and a red hard hat is working in a dark tunnel. The worker is illuminated by a bright light source, possibly a headlamp. The tunnel walls are dark and rocky. A yellow timestamp '2024/5/22' is visible in the bottom right corner of the image.

85	GX-B1309/21-5-24018	2024. 6. 12	综合判定：合格。	 <p>2024/5/22</p>
86	GX-B1309/21-5-24019	2024. 6. 12	综合判定：合格。	 <p>2024/5/22</p>
87	GX-B1309/21-5-24020	2024. 6. 12	综合判定：合格。	 <p>2024/5/22</p>

88	GX-B1495/20-5-241177-241180	2024. 6. 13	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
89	GX-B1310/21-5-24138	2024/6/13	符合标准要求。	