

序号	报告编号	发布日期	结论	影像资料
1	GX-B1539/22-7-24002	2024/11/28	所检项目合格。	 A photograph showing three workers in safety gear (hard hats and jackets) standing next to a yellow wheel loader inside a large industrial building or warehouse. The date stamp '2024/11/28' is visible in the bottom right corner of the image.
2	GX-B1539/22-7-24003	2024/11/28	所检项目合格。	 A photograph showing four workers in safety gear standing next to a yellow wheel loader outdoors. The background shows a dirt area and some trees. The date stamp '2024/11/28' is visible in the bottom right corner of the image.
3	GX-B1539/22-7-24004	2024/11/28	所检项目合格。	 A photograph showing a worker in safety gear standing next to a blue wheel loader. The date stamp '2024/11/28' is visible in the bottom right corner of the image.

4	GX-B1310/21-7-24078		符合标准要求。	
5	GX-B1310/21-7-24079		符合标准要求。	
6	GX-B1310/21-7-24080		符合标准要求。	

7	GX-B1424/20-7-24021	2024. 11. 29	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。			
8	GX-B1424/20-7-24022	2024. 11. 29	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。			